	Total	Time		nce Last rhaul	Linging ocivice and Walntenance
Date	Hours	Min	Hours	Min	Record maintenance actions including engine part removal special Inspections, Modifications and Service Bulletins
arried forward		<b>→</b>			
inled lot ward	1 1	2021	NEVD L	' Johnse 2	2002 8 R Engine
					2003.8 R Engine
1	V. I		•		spection And Was ———————————————————————————————————
		nined To	Be In An	Airworth	ny Condition.
	Richar	d Bridge:	A&P 339	12591	ge
<u></u>	<u> </u>	17 Feb :	2022 NS	KR Hob	obs: 2020.8 Re Eng: 583.1
		Drain The	en Service	Engine (	Oil W/* Ots Areoshell W100Plus And CH48109 Oil 511
		compres	sions #1-8	80/80 #2:	-80/80 #3-61/80 #4-65/80 #5-78/80#6-80/80 Class C
		and Kota	te Spark	Piugs. Ke	move Mags For Inspection. Installed Mags From Trans
		Airpower	· Florida. I	Rt Mag Si	#D18EA332R Left S#D18DA291R. Engine, Mag Timing
	1 1	20Degree	es BTC. Er	ngine Gro	ound Operation And Leak Check Successful, Oil Filter
	T	Clean, No	Debris.	Richard B	Bridges A&P 3392591 Kilust Bridge
	- 1	£			
17 Feb 2	2022 NS	KR Hob	bs: 2020	).8 Re E	ng: 583.1
And Mac	his Engine	Was Se	rviced An	d Inspect	ted IAW A Cessna 337 MM Annual Inspection
MIIU WAS	Determin	ea 10 Re	In An Air	worthy C	ondition.
Richard B	ridges IA	3392591	mu	y wo	
······································	indges i.A.	332331			
rain Then Se A48108 Oil I heck Succes ichard Bridg	Filter. Eng sful.	ne Ground	nd Operat		
	T				
			-		
4					

Ĩ

į

	Total 1	Гime	Time Sir Over	nce Last rhaul	Liquid oci vice dilli maintonan
Date	Hours	Min	Hours	Min	Record maintenance actions including engine part removal a Special Inspections, Modifications and Service Bulletins
Carried feetard -					- Junearing Survey
1: Remove	nce Performed #1 cylind	er due to	failure an	Mod	del:P337H SN: P3370335  d new cylinder. Ops and leak checks satisfactory at this time, Installed chooligies, Inc.
	58822A2BP C21AC574				
= 77			iii ii 3ti ati Oi	vas repaire n, and in re	ed and inspected in accordance with current regulations of the espect to the work performed, is approved for return to service IGNED
					AP3/10155
ĺ					
1. Approxing Ci	vil Aviation	2.		Αl	UTHORIZED RELEAS
Authority C	ountry:	-		1	FAA FORM 8130-3, AIRWORTHIN
FAATnite		ddress			NA Na Alabama 3
4. Organization	Continent	al Aerosp	ace Techi	nologies, li	nc. 2039 Broad Street, Mobile, Alabama 3
6. Item:	7. Desc	ription			8. Part Number.
1	CYL	& VAL	VE ASSY	LOADE	D, BAL   0388ZZRZBI
12 Remarks: AIRWO	RTHINES	S APPRO	OVAL		
Serial Batch Nu Serial AC21AC3		Descript	VALVE	Ser ASS AC	C21AC825 CYL & VALVE ASS
AC21AC5 AC21AC8	74 29	CYL&	VALVE VALVE	ASS AC	C21AC346 CYL & VALVE ASS C21BB905 CYL & VALVE ASS
AC21AC3 AC21BB9	21	CYL&	VALVE	ASS AG	C21AC143 CYL & VALVE ASS C21AC313 CYL & VALVE ASS
AC21AC4	96	CVI &	VALVE VALVE	ASS A	C21AC401 CYL & VALVE ASS
AC21ACC	20	CYL&	VALVE	ASS A	C21AC341 CYL & VALVE ASS
AC21AC	1/8				
AC21AC	1/8				
AC21AC	1/8				
AC21AC	1/8				
AC21AC	1/8				
AC21AC	1/8				

Data	Total	Time	Time Si	nce Last rhaul	Engine Service and Maintenance Record	
Date	Hours	Min	Hours	Min	Record maintenance actions including engine part removal and installation and compliance with in-	1
arried forward -		<b>→</b>			the state of the s	
			'			1 22 -
Date:10-19-22 Maintenance F	Performed:		1	Model: P	tenance Logbook Entry 2337H SN: P3370335  THANK YOU  Indinstalled new probe One shadow to the control of the co	4643
PN ON: 10-185 -SN ON: NSN	00	W OITI P.	robe aue u	o failure ar	이 Hotel How probe. Ops check satisfactory at this time	
	- <del></del>				d inspected in accordance with current regulations of the	3   [
Federa	The proposition of the second		rein was retration, and	u III IPSDAC	d inspected in accordance with current regulations of the	COST P.O. NO.
					AP3710155	
		₹/1			AD	UPS
E		4	N5KR Mod	Maintenan	nce Logbook Entry	m
e:11-28-22	Hobbs: 21	118.0	V2Nece	2011 1 22		P 18
intenance Perfor	med.				<b>D</b> 1 10	マー/宗
	med:				AYO	SHIPVIA
	med:	on IAW FA	AR43 appe	endix D wi	ith no defects noted.	
Performed 100hou	med: ur inspectio	·			ith no defects noted.	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and insp	ith no defects noted.  —end——————————————————————————————————	2
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	ith no defects noted.  —end——————————————————————————————————	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	ith no defects noted.  —end——————————————————————————————————	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
The Aircraf	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	
Performed 100hou	med: ur inspection ft identified ation Adm	d herein w	was repaire	ed and inspect to t	rett M. Boatenreiter	