



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
E062-221212 E1	LIGHT MAINTENANCE MANUAL - FJ44-1A - REVISION 66 - DEC 12/2022			MTH		-			
E062-221212 E2	LIGHT MAINTENANCE MANUAL - FJ44-1A - REVISION 66 - DEC 12/2022			MTH		-			
E062-230330 E1	REVIEW REVIEW FJ44-1A LMM REV 67			MTH		-			New Req
E062-230330 E2	REVIEW REVIEW FJ44-1A LMM REV 67			MTH		-			New Req
5-12-01 0512001B	INSPECTION DOCUMENT 01 KICT			MTH HRS LDG	01-Dec-2022 4248.5 3701	300		4548.5	294.7
5-12-02 0512002	INSPECTION DOCUMENT 02 KICT			MTH HRS LDG	01-Dec-2022 4248.5 3701	12		31-Dec-2023	8 m 3 d
B262201 COCKPIT 0512016	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER KICT		C352 E-92812368	MTH	01-Dec-2022	12		31-Dec-2023	8 m 3 d
5-12-04	INSPECTION DOCUMENT 04 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) KALN			MTH HRS LDG	22-Jan-2021 4152.4 3633	36			
A323101 0512004 : GEAR	RESTORATION (HYDROSTATIC TEST) EMERGENCY GEAR BOTTLE KALN		40005320-2/9912368- 2 3764	MTH	18-Dec-2020	36		31-Dec-2023	8 m 3 d
5-12-05	INSPECTION DOCUMENT 05 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) KALN			MTH HRS LDG	29-Nov-2022 4248.5 3701	60			
B262002 LEFT 0512005 : L	RESTORATION (HYDROSTATIC TEST) FIRE EXTINGUISHER BOTTLE KICT		30400031-1 37342B1	MTH	22-Nov-2022	60		30-Nov-2027	55 m 2 d
B262002 RIGHT 0512005 : R	RESTORATION (HYDROSTATIC TEST) FIRE EXTINGUISHER BOTTLE KICT		30400031-1 37467B1	MTH	22-Nov-2022	60		30-Nov-2027	55 m 2 d
5-12-06	INSPECTION DOCUMENT 06 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) SNL			MTH HRS LDG	16-May-2019 4028.5 3557	72			
A262201 COCKPIT 0512006	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER SNL		C352 E-92812368	MTH	15-May-2019	72		31-May-2025	25 m 3 d
5-12-07	INSPECTION DOCUMENT 07 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) KSNL			MTH HRS LDG	16-May-2019 4028.5 3557	144			
B262202 COCKPIT 0512007	RESTORATION (HYDROSTATIC TEST) PORTABLE FIRE EXTINGUISHER SNL		C352 E-92812368	MTH	15-May-2019	144		31-May-2031	97 m 3 d
5-12-08 0512008	INSPECTION DOCUMENT 08 KSNL			MTH HRS LDG	17-Mar-2022 4212.6 3677	24 300		31-Mar-2024 4512.6	11 m 3 d 258.8
5-12-09	INSPECTION DOCUMENT 09 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES) KICT			MTH HRS LDG	01-Dec-2022 4248.5 3701	4 200			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
A243301	FUNCTIONAL CHECK MAIN BATTERY LEAD ACID BATTERY (CAPACITY CHECK)	KICT	S3597-8 41019858	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		4 200		30-Apr-2023 4448.5	2 d 194.7
5-12-10 0512010	INSPECTION DOCUMENT 10	KALN		MTH 22-Jan-2021 HRS 4152.4 LDG 3633		36 1200		31-Jan-2024 5352.4	9 m 3 d 1098.6
5-12-11 0512011	INSPECTION DOCUMENT 11	KICT		MTH 01-Dec-2022 HRS 4248.5 LDG 3701		36 1200		31-Dec-2025 5448.5	32 m 3 d 1194.7
5-12-12 0512012	INSPECTION DOCUMENT 12 (14 CFR 91.207)	KICT	453-0150 65735	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		12		31-Dec-2023	8 m 3 d
5-12-13	INSPECTION DOCUMENT 13 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KICT		MTH 01-Dec-2022 HRS 4248.5 LDG 3701		24			
B341011 LEFT 0512013 : L	LEFT PITOT-STATIC SYSTEMS FUNCTIONAL CHECK (AIRPLANES -0003, -0360 AND ON AND AIRPLANES -0001 THRU -0359 INCORPORATING SB525-34-41)	KICT		MTH 28-Nov-2022		24		30-Nov-2024	19 m 2 d
B341011 RIGHT 0512013 : R	RIGHT PITOT-STATIC SYSTEMS FUNCTIONAL CHECK (AIRPLANES -0003, -0360 AND ON AND AIRPLANES -0001 THRU -0359 INCORPORATING SB525-34-41)	KICT		MTH 28-Nov-2022		24		30-Nov-2024	19 m 2 d
B345401 NO. 1 0512013 : 1	NO. 1 TRANSPONDER SYSTEM 14 CFR PART 91.413 CALIBRATION CHECK (EXCEPT PHILIPPINE REGISTERED AIRPLANES)	KICT	011-03303-00 3EH022843	MTH 27-Nov-2022		24		30-Nov-2024	19 m 2 d
B345401 NO. 2 0512013 : 2	NO. 2 TRANSPONDER SYSTEM 14 CFR PART 91.413 CALIBRATION CHECK (EXCEPT PHILIPPINE REGISTERED AIRPLANES)	KICT	011-03301-00 3EF021231	MTH 27-Nov-2022		24		30-Nov-2024	19 m 2 d
5-12-14	INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	SGF		MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		T/C			
A324103 LEFT 0512014 : L	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI)	SGF	3-1527-2 1265	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		T/C			
A324103 NOSE 0512014 : NOSE	SPECIAL DETAIL INSPECT LANDING GEAR WHEEL ASSY (NDI)	SGF	3-1418 5386P	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		T/C			
A324103 RIGHT 0512014 : R	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI)	SGF	3-1527-2 1224	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		T/C			
5-12-17	INSPECTION DOCUMENT 17 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KALN		MTH 16-Jan-2018 HRS 3944.8 LDG 3500		12 100			
5-12-18 0512018	INSPECTION DOCUMENT 18	KICT		MTH 01-Dec-2022 HRS 4248.5 LDG 3701		150		4398.5	144.7



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-21 <i>0512021</i>	INSPECTION DOCUMENT 21	KSNL		MTH 17-Mar-2022 HRS 4212.6 LDG 3677		24 600		31-Mar-2024 4812.6	11 m 3 d 558.8
5-12-22	INSPECTION DOCUMENT 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)								
		SGF		MTH 19-Dec-2016 HRS 3763.2 LDG 3332		300			
A361002 LEFT <i>0512022 : L</i>	DETAILED INSPECTION B/A PRECOOLER ASSEMBLY	SGF	8161-5 S4883T0782	MTH		N/R			
A361002 RIGHT <i>0512022 : R</i>	DETAILED INSPECTION B/A PRECOOLER ASSEMBLY	SGF	8161-5 S4883T0631	MTH		N/R			
5-12-29	INSPECTION DOCUMENT 29			MTH 19-Jun-2001 HRS 0		7200		7200	2946.2
5-12-33 <i>0512033</i>	INSPECTION DOCUMENT 33	KICT		MTH 01-Dec-2022 HRS 4248.5 LDG 3701		12 300		31-Dec-2023 4548.5	8 m 3 d 294.7
5-12-34 <i>0512034</i>	INSPECTION DOCUMENT 34 (NOT CURRENTLY USED)	AAF		MTH 01-May-2010 HRS 2263.6 LDG 2071 ACH 1150		N/R			
5-12-35 <i>0512035</i>	INSPECTION DOCUMENT 35 (NOT CURRENTLY USED)	TCL		MTH 15-May-2007 ACH 994		N/R			
5-12-36	INSPECTION DOCUMENT 36	KICT		MTH 01-Dec-2022 HRS 4248.5 LDG 3701		6		30-Jun-2023	2 m 2 d
5-12-MA <i>05120MA</i>	INSPECTION DOCUMENT MA	KICT		MTH 01-Dec-2022 HRS 4248.5 LDG 3701	-3.7	300		4544.8	291
5-12-MC <i>05120MC</i>	INSPECTION DOCUMENT MC	SGF		MTH 27-Jun-2016 HRS 3634.4 LDG 3229 ACH 2117.9		1200		4834.4	580.6
5-12-MD <i>05120MD</i>	INSPECTION DOCUMENT MD	*CF		MTH 19-Jun-2001 LDG 0		5000		5000	1299
5-12-MF <i>05120MF</i>	INSPECTION DOCUMENT MF	*CF		MTH 19-Jun-2001 HRS 0		6000		6000	1746.2
5-12-MG <i>05120MG</i>	INSPECTION DOCUMENT MG	*CF		MTH 19-Jun-2001 HRS 0		6000		6000	1746.2
5-12-MH <i>05120MH</i>	INSPECTION DOCUMENT MH	*CF		MTH 19-Jun-2001 HRS 0		6000		6000	1746.2
5-12-MI <i>05120MI</i>	INSPECTION DOCUMENT MI	*CF		MTH 19-Jun-2001 HRS 0		7200		7200	2946.2
5-12-MJ <i>05120MJ</i>	INSPECTION DOCUMENT MJ	*CF		MTH 19-Jun-2001 HRS 0		7200		7200	2946.2
5-12-MK <i>05120MK</i>	INSPECTION DOCUMENT MK	*CF		MTH 19-Jun-2001 HRS 0		7900		7900	3646.2
5-12-MM <i>05120MM</i>	INSPECTION DOCUMENT MM	*CF		MTH 19-Jun-2001 HRS 0		12000		12000	7746.2
5-12-MN <i>05120MN</i>	INSPECTION DOCUMENT MN	*CF		MTH 19-Jun-2001 HRS 0		12000		12000	7746.2
5-12-MO <i>05120MO</i>	INSPECTION DOCUMENT MO	*CF		MTH 19-Jun-2001 HRS 0		15200		15200	10946.2
5-12-MQ	INSPECTION DOCUMENT MQ			MTH HRS		14000		14000	9746.2



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
A551004 045503	HORIZONTAL STABILIZER FRONT UPPER SPAR CAP AT SS4.78 INSPECTION TASK 55-10-00-250 *CF			MTH 19-Jun-2001 HRS 0		14000		14000	9746.2
5-12-MR	INSPECTION DOCUMENT MR			MTH HRS		13200		13200	8946.2
A570006 045701	LOWER MAIN SPAR SPLICE AT WS 93.00 (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-250 *CF			MTH 19-Jun-2001 HRS 0		13200		13200	8946.2
5-12-MS	INSPECTION DOCUMENT MS			MTH HRS		15000		15000	10746.2
A570007 045702	LOWER REAR SPAR SPLICE AT WS 93.00 (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-251 *CF			MTH 19-Jun-2001 HRS 0		15000		15000	10746.2
5-12-MT	INSPECTION DOCUMENT MT			MTH HRS		19200		19200	14946.2
A570008 045703	MAIN SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-252 *CF			MTH 19-Jun-2001 HRS 0		19200		19200	14946.2
5-12-MU	INSPECTION DOCUMENT MU			MTH HRS		19200		19200	14946.2
A570009 045704	REAR SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0) (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-253 *CF			MTH 19-Jun-2001 HRS 0		19200		19200	14946.2
5-12-MV	INSPECTION DOCUMENT MV			MTH HRS		22800		22800	18546.2
A570010 045705	MAIN SPAR OUTBOARD LOWER CAP (WS 120.0 TO WS 152.00) (EDDY CURRENT) SPECIAL DETAILED INSPECTION TASK 57-00-00-254 *CF			MTH 19-Jun-2001 HRS 0		22800		22800	18546.2
05-50-00-870-803-01 E1	POLISH FAN ROTOR			MTH 19-Jun-2001		A/R			
05-50-00-870-803-01 E2	POLISH FAN ROTOR			MTH 19-Jun-2001		A/R			
052001 E1	FJ44 CHECK 1	KICT		MTH 01-Dec-2022 HRS 4247.2 LDG 3701		300		4547.2	293.4
052001 E2	FJ44 CHECK 1	KICT		MTH 01-Dec-2022 HRS 4248.5 LDG 3701		300		4548.5	294.7
052002 E1	FJ44 CHECK 2	KICT		MTH 01-Dec-2022 HRS 4247.2 LDG 3701		600		4847.2	593.4
052002 E2	FJ44 CHECK 2	KICT		MTH 01-Dec-2022 HRS 4248.5 LDG 3701		600		4848.5	594.7
052003 E1	FJ44 CHECK 3			MTH 18-Apr-2008 HRS 1810.7		-			
052003 E2	FJ44 CHECK 3			MTH 18-Apr-2008 HRS 1786.5		-			
052004 E1	FJ44 CHECK 4	MCO		MTH 19-Jun-2001 HRS 24.2		5000		5024.2	770.4
052004 E2	FJ44 CHECK 4	SWF		MTH 19-Jun-2001 HRS 0		5000		5000	746.2
052005 E1	FJ44 CHECK 5			MTH 19-Jun-2001 HRS 24.2		8500		8524.2	4270.4
052005 E2	FJ44 CHECK 5			MTH 19-Jun-2001 HRS 0		8500		8500	4246.2

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
052006 E1	FJ44 CHECK 6		MTH	19-Jun-2001					
			HRS	24.2		10000		10024.2	5770.4
052006 E2	FJ44 CHECK 6		MTH	19-Jun-2001					
			HRS	0		10000		10000	5746.2
052007 E1	FJ44 CHECK 7		MTH	19-Jun-2001					
			HRS	24.2		13500		13524.2	9270.4
052007 E2	FJ44 CHECK 7		MTH	19-Jun-2001					
			HRS	0		13500		13500	9246.2
052008 E1	FJ44 CHECK 8		MTH	19-Jun-2001					
			HRS	24.2		15000		15024.2	10770.4
052008 E2	FJ44 CHECK 8		MTH	19-Jun-2001					
			HRS	0		15000		15000	10746.2
052009 E1	FJ44 CHECK 9		MTH	19-Jun-2001					
			HRS	24.2		18500		18524.2	14270.4
052009 E2	FJ44 CHECK 9		MTH	19-Jun-2001					
			HRS	0		18500		18500	14246.2
052010 E1	FJ44 CHECK 10		MTH	19-Jun-2001					
			HRS	24.2		20000		20024.2	15770.4
052010 E2	FJ44 CHECK 10		MTH	19-Jun-2001					
			HRS	0		20000		20000	15746.2
12-22-01-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH								
			DAYS	19-Jun-2001		A/R			
12-22-01-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH								
			DAYS	19-Jun-2001		A/R			
12-22-01-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH								
			DAYS	19-Jun-2001		A/R			
262002A LEFT NO. 1 262002 : L1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) KICT		AE13083-5 9826	MTH	29-Nov-2022				
				HRS	4248.5	96		30-Nov-2030	91 m 2 d
				LDG	3701				
262002C LEFT NO. 2 262002 : L2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) KICT		AE13083-5 9828	MTH	29-Nov-2022				
				HRS	4248.5	96		30-Nov-2030	91 m 2 d
				LDG	3701				
262002E RIGHT NO. 1 262002 : R1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) KICT		AE13083-5 9829	MTH	29-Nov-2022				
				HRS	4248.5	96		30-Nov-2030	91 m 2 d
				LDG	3701				
262002G RIGHT NO. 2 262002 : R2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) KICT		AE13083-5 9830	MTH	29-Nov-2022				
				HRS	4248.5	96		30-Nov-2030	91 m 2 d
				LDG	3701				
B335003 LEFT	LEFT EMERGENCY LIGHTING BATTERY PACK RESTORATION KICT		CBS28-1 3999M	MTH	29-Nov-2022				
				HRS	4248.5	48		30-Nov-2026	43 m 2 d
				LDG	3701				
341055 LEFT 0512013 : L-ADC	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411) KICT		822-1109-002 2VC6R	MTH	28-Nov-2022				
						A/R			
341058 RIGHT 0512013B : R-ADC	CALIBRATION TEST ADC/ALT UNIT (FAR 91.411) KICT		70251N02D04 04051427D	MTH	28-Nov-2022				
						A/R			
342012A STANDBY 0512013B : STDBY	CALIBRATION TEST AIRSPEED ALTIMETER (FAR 91.411) KICT		WL102AMS6 AN119	MTH	28-Nov-2022				
						A/R			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
<i>350002</i> <i>0512004 : OXY</i>	RESTORATION (HYDROSTATIC TEST) OXYGEN BOTTLE			176274-22 ALT280-5623/1438	MTH 26-Jan-2021		60		31-Jan-2026	33 m 3 d
350003	HYDROSTATIC TEST PORTABLE OXYGEN CYLINDER (DOT3AA)			PN SN-UNKNOWN			N/R			
350004	HYDROSTATIC TEST OXYGEN BOTTLE (DOT SP-10945)			176274-22 ALT280-5623/1438			N/R			
710010 E1	COMPRESSOR CLEANING				MTH 19-Jun-2001		A/R			
710010 E2	COMPRESSOR CLEANING				MTH 19-Jun-2001		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211003	HEAT PRESSURE EXCHANGER *CF			10840A 595	MTH 19-Jun-2001		O/C			
211004	RAM AIR MODULATING VALVE KRST			27241287-24 7AT40	MTH 17-Sep-2014 HRS 3032.3 LDG 2704		O/C	0 0		
211005	EMERGENCY PRESS SHUTOFF VALVE 9912422-2 *CF			2601-23 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
212001	UNDERFLOOR INLET AIR BLOWER *CF			0113-12 0525	MTH 19-Jun-2001		O/C			
212003	TEMP PRESS COMPRESSION SWITCH *CF			1173T42-3 3008	MTH 19-Jun-2001		O/C			
212011 AFT	TEMP UNDERFLOOR SENSOR 9912085-3 *CF			27221274 0133	MTH 19-Jun-2001		O/C			
212202	OVERHEAD AIR VALVE SOLENOID *CF			D113204 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
212203	ACTUATOR *CF			D-68070-A-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
212302	BLOWER - WINDSHIELD AIR MOTOR *CF			7003-200 0672	MTH 19-Jun-2001		O/C			
212404 NOSE	AVIONICS COOLING FAN *CF			032105 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
213001	PRESS MASTER OUTFLOW VALVE 9912409-18 KALN E			52771-331 1026	MTH 15-Oct-2012 HRS 2476.9 LDG 2277		O/C	0 0 0		
213002	PRESS SECONDARY OUTFLOW VALVE PDK			52772-001 314	MTH 22-Jul-2008 HRS 1916		O/C	0		
213003	PRESSURIZATION CONTROLLER 9912409-6 ICT			52770-112 1188	MTH 16-Oct-2012 HRS 2478.4 LDG 2280		O/C			
213005	DIFFERENTIAL PRESS INDICATOR *CF			C668511-0105 21576	MTH 19-Jun-2001		O/C			
213008	PRESS MANUAL CONTROL SWITCH 9912409-4 *CF			52773-001 1058	MTH 19-Jun-2001		O/C			
215001	FORWARD EVAPORATOR 9912459-9 SGF			1134820-13 332	MTH 30-Apr-2015 HRS 3287.3 LDG 2912		O/C	0 0		
215002	AFT EVAPORATOR 9912459-10 KFTW			1134820-14 228	MTH 10-Sep-2016 HRS 3675.2 LDG 3266 ACH 2162.9		O/C			
215003 AFT	EVAPORATOR MOTOR *CF			1250210-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
215003 FORWARD	EVAPORATOR MOTOR *CF			1250210-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
215004	AIR CONDITIONER COMPRESSOR KSNL			9912459-8 696A	MTH 29-Jul-2021 HRS 4181.6 LDG 3654		O/C	0 0 0		
215005	AIR CONDITIONER CONDENSER KSNL			1134180-1 N/A	MTH 29-Jul-2021 HRS 4181.6 LDG 3654		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
215006	COMPRESSOR DRIVE MOTOR KSNL	KSNL		1134103-1 N/A	MTH 29-Jul-2021 HRS 4181.6 LDG 3654		O/C	0 0		
215007	RECEIVER DRYER ASSEMBLY KSNL	KSNL		1134140-3 N/A	MTH 29-Jul-2021 HRS 4181.6 LDG 3654		O/C	0 0		
215008	BINARY SWITCH 9912459-8 (R134A)	KSNL		1250232-12 N/A	MTH 29-Jul-2021 HRS 4181.6 LDG 3654		O/C	0 0		
215009	A/C FLIGHT HOUR METER *CF			1250703-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
215010	FREON A/C-BAROMETRIC SWITCH KSNL	KSNL		GBC300-82 N/A	MTH 29-Jul-2021 HRS 4181.6 LDG 3654		O/C	0 0		
215011	AIR CONDITIONER DRIVE BELT R134A	KSNL		232L100 N/A	MTH 29-Jul-2021 HRS 4181.6 LDG 3654		O/C	0 0		
215012	COMPRESSOR DRIVE MOTOR BRUSHES KSNL	KSNL		1251171 N/A	MTH 29-Jul-2021 HRS 4181.6 LDG 3654 ACH 2433.8		500	0	2933.8	500
215013 AFT	EXPANSION VALVE *CF	*CF		1250218 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
215013 FORWARD	EXPANSION VALVE *CF	*CF		1250218 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
216002	TEMPERATURE CONTROLLER SGF	SGF		1E58-6 4BK5	MTH 07-Oct-2014 HRS 3056.5 LDG 2725		O/C	0 0		
216003	TEMP CNTL SYS SENSOR 9912085-3	*CF		27221274 2AU69	MTH 19-Jun-2001		O/C			
221003 AILERON	SERVO	ICT		822-1168-002 33RDB	MTH 27-Feb-2013 HRS 2575.1 LDG 2344		O/C	1 0 0		
221004 RUDDER	SERVO	KSGF		822-1168-001 2YP3R	MTH 14-Feb-2013 HRS 2562.1 LDG 2337		O/C	0 0 0		
221005 ELEVATOR	SERVO	KICT		822-1168-001 3LK7T	MTH 22-Jul-2012 HRS 2442.9 LDG 2249		O/C	0 0 0		
221006 AILERON	SERVO MOUNT *CF	*CF		622-5735-021 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
221006 ELEVATOR	SERVO MOUNT *CF	*CF		622-5735-020 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
221006 RUDDER	SERVO MOUNT	KALN		622-5735-022 4KVDF0	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		O/C	0 0		
221008	AUTOPILOT CONTROL APP-85	*CF		622-6208-227 CRMJ	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
232001 NO. 1	COMM RADIO SYSTEM CONTROL KY-196B	SGF		064-01084-0201 4354	MTH 07-Nov-2017 HRS 3936.7 LDG 3492 ACH 2302.9		O/C			
232001 NO. 2	COMM RADIO SYSTEM CONTROL KY-196B	SGF		064-01084-0201 2949	MTH 06-Nov-2017 HRS 3936.7 LDG 3492 ACH 2300.3		O/C			
232008 BOTTOM	ANTENNA - COMM 1	*CF		17-40-02W 0305	MTH 19-Jun-2001		O/C			
232008 TOP	ANTENNA - COMM 2	KALN		18-50-01 1243	MTH 10-Jun-2016 HRS 3616.7 LDG 3210		O/C	0 0		
235001 LEFT	AUDIO AMPLIFIER S3100-64	*CF	C	5646-1 437	MTH 19-Jun-2001		O/C			
235001 RIGHT	AUDIO AMPLIFIER S3100-64	*CF	C	5646-1 438	MTH 19-Jun-2001		O/C			
243001	BATTERY TEMP INDICATOR *CF			1229-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
243002 LEFT	GENERATOR CONTROL UNIT *CF			51525-001F Y1106	MTH 19-Jun-2001		O/C			
243002 RIGHT	GENERATOR CONTROL UNIT *CF			51525-001F Y1080	MTH 19-Jun-2001		O/C			
243003	MAIN BATTERY	KALN		S3597-8 41019858	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		O/C			
243004	BATTERY TEMPERATURE MONITOR- SGF			1529-1-1 3089	MTH 03-Dec-2015 HRS 3509 LDG 3112 ACH 2079.1		O/C			
243005	OVERVOLTAGE MONITOR- *CF			1645-1-3 2547	MTH 19-Jun-2001		O/C			
243006 LEFT	AMMETER *CF			C662501-0105 J20835	MTH 19-Jun-2001		O/C			
243006 RIGHT	AMMETER *CF			C662501-0105 B21262	MTH 19-Jun-2001		O/C			
243008	BATTERY DISCONNECT RELAY KALN			A-931F CG-28274	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		O/C			
243011	VOLTMETER *CF			C662502-0101 J20851	MTH 19-Jun-2001		O/C			
245001 LEFT	START PCB ASSY *CF			6318324-6 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245001 RIGHT	START PCB ASSY *CF			6318324-6 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245002 LEFT	ASSEMBLY-FUEL CONTROL PCB *CF			6318321-4 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245002 RIGHT	ASSEMBLY-FUEL CONTROL PCB *CF			6318321-4 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245003 LEFT	ASSEMBLY-IGNITOR PCB *CF			6318322-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245003 RIGHT	ASSEMBLY-IGNITOR PCB *CF			6318322-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
245004 LEFT	ANTI ICE PCB ASSY *CF			6318323-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245004 RIGHT	ANTI ICE PCB ASSY *CF			6318323-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245005	ATTENUATOR PCB ASSY SGF			6318355-2 N/A	MTH 30-Oct-2012 HRS 2489.2 LDG 2290		O/C	0 0 0		
245006	ENVIRONMENTAL PCB ASSY *CF			6318356-2 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245007	MISCELLANEOUS PCB ASSY *CF			6318357-2 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245008	TRIM CONTROL PCB ASSY *CF			6518351-9 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245009	DIMMING PCB ASSY SMF			6518353-4 0774	MTH 26-Aug-2002 HRS 75		O/C	0		
245010	GEAR LOGIC PCB ASSY *CF			6518354-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
245011	FUEL FLOW XMITTER PCB ASSY 9912417-2 *CF			85-230-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
256001	ELT TRANSMITTER ELT-110-4 ARTEX *CF			453-0150 65735	MTH 19-Jun-2001		O/C			
256004	ELT ANTENNA *CF			DMQ18-3 9292	MTH 19-Jun-2001		O/C			
256005	ELT BEACON BATTERY PACK KICT			452-0130 394466-013	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		24	0 0 0	31-Mar-2025	23 m 3 d
256006 CO-PILOT	LIFE VEST KALN			P01202-101 20100740002	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		60	0	31-Jan-2026	33 m 3 d
256006 NO. 1	LIFE VEST KALN			P01202-101 20100740004	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		60	0	31-Jan-2026	33 m 3 d
256006 NO. 2	LIFE VEST KALN			P01202-101 20100740007	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		60	0	31-Jan-2026	33 m 3 d
256006 NO. 3	LIFE VEST KALN			P01202-101 20100740003	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		60	0	31-Jan-2026	33 m 3 d
256006 NO. 4	LIFE VEST KALN			P01202-101 20100740006	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		60	0	31-Jan-2026	33 m 3 d
256006 NO. 5	LIFE VEST KALN			P01202-101 20100740005	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		60	0	31-Jan-2026	33 m 3 d
256006 PILOT	LIFE VEST KALN			P01202-101 20100740001	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		60	0	31-Jan-2026	33 m 3 d
261002 LEFT	FIRE DETECT SENSOR 9912416-1 *CF			30012121004/4559 203756	MTH 19-Jun-2001		O/C			
261002 RIGHT	FIRE DETECT SENSOR 9912416-1 *CF			30012121004/4559 203744	MTH 19-Jun-2001		O/C			
262001 LEFT	FIRE EXTINGUISHER BOTTLE 9912048-4 SGF			30400031-1 37342B1	MTH 10-Apr-2017 HRS 3810.5 LDG 3374 ACH 2216.3		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
262001 RIGHT	FIRE EXTINGUISHER BOTTLE 9912048-4	SGF		30400031-1 37467B1	MTH 10-Apr-2017 HRS 3810.5 LDG 3374 ACH 2216.3		O/C			
262002 LEFT NO. 1	FIRE EXTINGUISHER CARTRIDGE KICT			AE13083-5 9826	MTH 01-Dec-2022 HRS 4248.5 LDG 3701	63	120	0 0	30-Sep-2032	113 m 2 d
Manufacture Date: 30-Jun-2022										
262002 LEFT NO. 2	FIRE EXTINGUISHER CARTRIDGE KICT			AE13083-5 9828	MTH 01-Dec-2022 HRS 4248.5 LDG 3701	63	120	0 0	30-Sep-2032	113 m 2 d
Manufacture Date: 30-Jun-2022										
262002 RIGHT NO. 1	FIRE EXTINGUISHER CARTRIDGE KICT			AE13083-5 9829	MTH 01-Dec-2022 HRS 4248.5 LDG 3701	63	120	0 0	30-Sep-2032	113 m 2 d
Manufacture Date: 30-Jun-2022										
262002 RIGHT NO. 2	FIRE EXTINGUISHER CARTRIDGE KICT			AE13083-5 9830	MTH 01-Dec-2022 HRS 4248.5 LDG 3701	63	120	0 0	30-Sep-2032	113 m 2 d
Manufacture Date: 30-Jun-2022										
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER SNL			C352 E-92812368	MTH 16-May-2019 HRS 4028.5 LDG 3557		O/C	0 0		
273001 LEFT	SHAKER CONTROL *CF			201 4835	MTH 19-Jun-2001		O/C			
273002	ELEVATOR ELECTRIC TRIM SERVO *CF	4		44430-3548 T617	MTH 19-Jun-2001		O/C			
273003	SERVO MOUNT ASSY *CF			44575-3415 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
273004 LEFT	ELEVATOR TRIM ACTUATOR *CF			6361215-21 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
273004 RIGHT	ELEVATOR TRIM ACTUATOR *CF			6361215-22 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
273005	RUDDER TRIM TAB ACTUATOR *CF			6361215-21 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
275001	SHUTOFF VALVE *CF			4083-1 071	MTH 19-Jun-2001		O/C			
275002 LEFT	FLAP HYD ACTUATOR 9912365-5 *CF			1542000-7 1004	MTH 19-Jun-2001		O/C			
275002 RIGHT	FLAP HYD ACTUATOR 9912365-5 *CF			1542000-7 0999	MTH 19-Jun-2001		O/C			
276001 LEFT	SPEEDBRAKE ACTUATOR 9912375-4 *CF			1542100-5 1027	MTH 19-Jun-2001		O/C			
276001 RIGHT	SPEEDBRAKE ACTUATOR 9912375-4 *CF			1542100-5 0984	MTH 19-Jun-2001		O/C			
281001 LEFT	FUEL SURGE VALVE 9912016-2 *CF			35C10D 1899	MTH 19-Jun-2001		O/C			
281001 RIGHT	FUEL SURGE VALVE 9912016-2 *CF			35C10D 1914	MTH 19-Jun-2001		O/C			
282001 LEFT	ELECTRIC FUEL PUMP 9912017-4 *CF			1C7-13 3AU29	MTH 19-Jun-2001		O/C			
282001 RIGHT	ELECTRIC FUEL PUMP 9912017-4 *CF			1C7-13 3AU33	MTH 19-Jun-2001		O/C			
282002 LEFT	FUEL TRANSFER PUMP 9912190-3 *CF			RG45880 B1014	MTH 19-Jun-2001		O/C			
282002 RIGHT	FUEL TRANSFER PUMP 9912190-3 *CF			RG45880 B1020	MTH 19-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
282004 LEFT	FUEL MOTOR ACTUATED VALVE 9912014-3	*CF		EM9014-3 979	MTH 19-Jun-2001		O/C			
282004 RIGHT	FUEL MOTOR ACTUATED VALVE 9912014-3	*CF		EM9014-3 952	MTH 19-Jun-2001		O/C			
282005 LEFT	FUEL TRANSFER EJECTOR 9912190-2	*CF		RG45310 B8226	MTH 19-Jun-2001		O/C			
282005 RIGHT	FUEL TRANSFER EJECTOR 9912190-2	*CF		RG45310 B8237	MTH 19-Jun-2001		O/C			
282006	TRANSFER VALVE 9914103-6	*CF		ZSV57 01114297	MTH 19-Jun-2001		O/C			
284001 LEFT	#5 FUEL TRANSMITTER 9912412-5	*CF		10307T01Y00 1059	MTH 19-Jun-2001		O/C			
284001 RIGHT	#5 FUEL TRANSMITTER 9912412-5	*CF		10307T01Y00 1062	MTH 19-Jun-2001		O/C			
284002 LEFT	FUEL QUANTITY TRANSMITTER 9912412-8	*CF		10309T03Y00 1243	MTH 19-Jun-2001		O/C			
284002 RIGHT	FUEL QUANTITY TRANSMITTER 9912412-8	*CF		10309T03Y00 1244	MTH 19-Jun-2001		O/C			
284003	FUEL QUANTITY SIGNAL CONDITIONER 9912412-7			10310B01Y02 207	MTH 21-Jul-2004 HRS 463		O/C	0		
284004 LEFT	#3 FUEL TRANSMITTER 9912412-3	*CF		10305T01Y00 1070	MTH 19-Jun-2001		O/C			
284004 RIGHT	#3 FUEL TRANSMITTER 9912412-3	*CF		10305T01Y00 1077	MTH 19-Jun-2001		O/C			
284005 LEFT	#4 FUEL TRANSMITTER 9912412-4	*CF		10306T01Y00 1066	MTH 19-Jun-2001		O/C			
284005 RIGHT	#4 FUEL TRANSMITTER 9912412-4	*CF		10306T01Y00 1070	MTH 19-Jun-2001		O/C			
284006 LEFT	#2 FUEL TRANSMITTER 9912412-2	*CF		10304T01Y00 1096	MTH 19-Jun-2001		O/C			
284006 RIGHT	#2 FUEL TRANSMITTER 9912412-2	*CF		10304T01Y00 B1061	MTH 19-Jun-2001		O/C			
284007 LEFT	#1 FUEL TRANSMITTER 9912412-1	*CF		10303T01Y00 B1044	MTH 19-Jun-2001		O/C			
284007 RIGHT	#1 FUEL TRANSMITTER 9912412-1	*CF		10303T01Y00 B1048	MTH 19-Jun-2001		O/C			
284008 LEFT	FUEL LOW LEVEL SWITCH KALN			GIF5400-40 NSN	MTH 16-Jan-2018 HRS 3944.8 LDG 3500 ACH 2305.1		O/C	0	0	
284008 RIGHT	FUEL LOW LEVEL SWITCH SGF			GIF5400-40 NSN	MTH 17-Mar-2015 HRS 3246.5 LDG 2884		O/C	0	0	
291002 LEFT	HYDRAULIC PUMP ASSY KALN			4120-021007 388A	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		O/C	0	0	
291002 RIGHT	HYDRAULIC PUMP ASSY 4120-021003 KALN			9912392-2 446A	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		O/C	0	0	
291003	HYDRAULIC CHECK VALVE *CF			CV02-193 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
291005	HYDRAULIC RESERVOIR ASSEMBLY *CF			6317001-54 SN-UNKNOWN	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
291007	PRESSURE SWITCH 9912373-4	*CF		GPP1250-58 041090	MTH 19-Jun-2001		O/C			
291008	HYDRAULIC MANIFOLD ASSEMBLY 9912423-40	*CF		8184-12 486	MTH 19-Jun-2001		O/C			
291009	HYDRAULIC RELIEF VALVE 9912400-4	*CF		1785-1 481	MTH 19-Jun-2001		O/C			
291010 LEFT	HYDRAULIC SHUTOFF VALVE ASSY 9912400-4	*CF		AV24B1388-2 T91079	MTH 19-Jun-2001		O/C			
291010 RIGHT	HYDRAULIC SHUTOFF VALVE ASSY 9912400-4	*CF		AV24B1388-2 T91080	MTH 19-Jun-2001		O/C			
291011 LEFT	FLOW SWITCH/CHECK HYD VALVE 9912393-3	*CF		MC19251 0156	MTH 19-Jun-2001		O/C			
291011 RIGHT	FLOW SWITCH/CHECK HYD VALVE 9912393-3	*CF		MC19251 0097	MTH 19-Jun-2001		O/C			
291011	SYSTEM RELIEF VALVE 9912423-38	*CF		2576-1 102C	MTH 19-Jun-2001		O/C			
291012	SPEED BRAKE DUMP VALVE SOLENOID 9912423-33	*CF		4082-6 099	MTH 19-Jun-2001		O/C			
291013	LOADING VALVE SOLENOID 9912423-39	*CF		4134-4 095	MTH 19-Jun-2001		O/C			
291014	GEAR VALVE SOLENOID 9912423-35	*CF		4051-3 097	MTH 19-Jun-2001		O/C			
291015	GEAR PORTION CHECK VALVE 9912423-13	*CF		9504 097	MTH 19-Jun-2001		O/C			
291016 LEFT	SPEED BRAKE PORTION VALVE 9912423-14	*CF		9505 194	MTH 19-Jun-2001		O/C			
291016 RIGHT	SPEED BRAKE PORTION VALVE 9912423-14	*CF		9505 195	MTH 19-Jun-2001		O/C			
291017	SPEED BRAKE PORTION VALVE 9912423-32	*CF		2577-1 097	MTH 19-Jun-2001		O/C			
291018	PNEUMATIC DUMP VALVE 9912423-34	*CF		9503-2 097	MTH 19-Jun-2001		O/C			
291019 LEFT	ATTENUATOR VALVE SOLENOID 9912423-28	*CF		4107-3 097	MTH 19-Jun-2001		O/C			
291019 RIGHT	ATTENUATOR VALVE SOLENOID 9912423-27	*CF		4107-4 097	MTH 19-Jun-2001		O/C			
291020 NO. 1	SPEEDBRAKE VALVE SOLENOID 9912423-30	*CF		4052-3 097	MTH 19-Jun-2001		O/C			
291021 NO. 1	FLAP VALVE SOLENOID 9912423-29	*CF		4052-4 097	MTH 19-Jun-2001		O/C			
291022	ELECTRO/HYDRAULIC SERVO VALVE 9912403-2	*CF		37-509 455	MTH 19-Jun-2001		O/C			
301001	SHUTOFF ISOLATION VALVE 9912403-2	*CF		2602-36 0510	MTH 19-Jun-2001		O/C			
301002 LEFT	PNEUMATIC DEICE SWITCH 9912402-9	*CF		1106P55-1 1501A	MTH 19-Jun-2001		O/C			
301002 RIGHT	PNEUMATIC DEICE SWITCH 9912402-9	*CF		1106P55-1 1511A	MTH 19-Jun-2001		O/C			
301003 LEFT	SHUTOFF PRESS REGULATOR VALVE 9912402-9	*CF		1H127-4 2AU33	MTH 19-Jun-2001		O/C			
301003 RIGHT	SHUTOFF PRESS REGULATOR VALVE 9912402-9	*CF		1H127-4 1AU4	MTH 19-Jun-2001		O/C			
301004 LEFT	TEMPERATURE DEICE SWITCH 9912402-9	*CF		1173T42-4 1368	MTH 19-Jun-2001		O/C			
301004 RIGHT	TEMPERATURE DEICE SWITCH 9912402-9	*CF		1173T42-4 1369	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301010 LEFT	HORIZONTAL STABILIZER BOOT	SGF		29S4D5244-11 NCJ8320	MTH 20-Feb-2015 HRS 3206 LDG 2851		O/C	0		0
301010 RIGHT	HORIZONTAL STABILIZER BOOT	KALN		P29S-4D5244-12 NFR2290	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		O/C	0		0
301011	DEICE TAIL TIMER 9912440-1	*CF		937-1-1 0113074	MTH 19-Jun-2001		O/C			
302001 LEFT	SOLENOID VALVE 9912402-10	*CF		1H127-5 3AU17	MTH 19-Jun-2001		O/C			
302001 RIGHT	SOLENOID VALVE 9912402-10	*CF		1H127-5 2AU9	MTH 19-Jun-2001		O/C			
302003 LEFT	INLET MONITOR SWITCH *CF			21542-2-68-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
302003 RIGHT	INLET MONITOR SWITCH *CF			21542-2-68-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
303002 LEFT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
303002 RIGHT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
304001	B/A TEMP MONITOR- *CF			1169-1 306	MTH 19-Jun-2001		O/C			
304002	HEAT EXCHANGER 9912041-3	*CF		10653A 1236	MTH 19-Jun-2001		O/C			
304003	WINDSHIELD S/O VALVE 9912402-9	*CF		1H127-4 10AT163	MTH 19-Jun-2001		O/C			
304004 LEFT	PITOT STATIC CURRENT SENSOR *CF			76250-1 4336	MTH 19-Jun-2001		O/C			
304004 RIGHT	PITOT STATIC CURRENT SENSOR *CF			76250-1 4265	MTH 19-Jun-2001		O/C			
304006	TEMP BLEED AIR CONTROLLER 9912085-6	*CF		1E58-1 2AU23	MTH 19-Jun-2001		O/C			
304007	TEMP CONTROL BLEED AIR VALVE 9912085-1	*CF		27241287 12AT166	MTH 19-Jun-2001		O/C			
304009 LEFT	SOLENOID DEICE VALVE *CF			3D2353-06 N17536	MTH 19-Jun-2001		O/C			
304009 RIGHT	SOLENOID DEICE VALVE *CF			3D2353-06 N17771	MTH 19-Jun-2001		O/C			
304010	ALCOHOL PUMP ASSEMBLY *CF			476411 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
304011	TEMPERATURE SENSOR 9912085-3	*CF		27221274 8AT320	MTH 19-Jun-2001		O/C			
304012 LEFT	WINDSHIELD BLEED AIR VALVE *CF			1403-25 2525	MTH 19-Jun-2001		O/C			
304012 RIGHT	WINDSHIELD BLEED AIR VALVE *CF			1403-25 2528	MTH 19-Jun-2001		O/C			
304013	PRESSURE WINDSHIELD SWITCH *CF			1115P25 3497AB	MTH 19-Jun-2001		O/C			
304014 AFT	TEMPERATURE EVAPORATOR SENSOR 9912085-3	*CF		27221274 12AT478	MTH 19-Jun-2001		O/C			
312001 LEFT	DIGITAL CLOCK *CF			M877A5V 12242	MTH 19-Jun-2001		O/C			
313001	FLIGHT HOUR METER 85071	*CF		C664503-0104 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
315001	CABIN ALTITUDE PRESSURE SWITCH 9910095-6	*CF		GB300NA161 0112632	MTH 19-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
315002	MASTER WARN ANNUNCIATOR ASSY *CF			9912438-21 533	MTH 19-Jun-2001		O/C			
321001 LEFT MAIN LANDING GEAR	AND ATTACHING HARDWARE ASSEMBLY *CF			6341003-13 046	MTH 19-Jun-2001		O/C			
321001 NOSE LANDING GEAR	STRUT AND ATTACHING HARDWARE ASSEMBLY *CF			6342000-26 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		22500	0	22500	18799
321001 RIGHT MAIN LANDING GEAR <i>321002 : R</i>	AND ATTACHING HARDWARE ASSEMBLY *CF			6341003-14 049	MTH 19-Jun-2001		O/C			
321003 LEFT MAIN GEAR <i>321003A : L</i>	TRUNNION ASSEMBLY *CF			6341007-5 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		10346	0	10346	6645
321004 RIGHT MAIN GEAR <i>321004A : R</i>	TRUNNION ASSEMBLY *CF			6341007-6 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		10346	0	10346	6645
321005 LEFT <i>321005A : L</i>	TRAILING LINK AND AXLE ASSEMBLY *CF			6341002-7 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
321006 RIGHT <i>321006A : R</i>	TRAILING LINK AND AXLE ASSEMBLY *CF			6341002-8 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
321007	SHIMMY DAMPER ASSEMBLY *CF			6343001-7 0917	MTH 19-Jun-2001		O/C			
321008 LEFT <i>321008A : L</i>	OLEO ASSEMBLY *CF			6341130-5 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
321008 RIGHT <i>321008A : R</i>	OLEO ASSEMBLY *CF			6341130-5 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
321009 <i>321004</i>	FORK AND PISTON ASSEMBLY *CF			6342000-3 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		12500	0	12500	8799
323000 NOSE LANDING GEAR <i>323001</i>	ACTUATOR ASSEMBLY 1541900-7	KSGF		9912370-5 1636	MTH 23-Aug-2013 HRS 2725.7 LDG 2450		7500	0	9950	6249
323001 LEFT MAIN LANDING GEAR <i>323001A : L</i>	ACTUATOR ASSEMBLY 9912397-8	*CF		1541800-13 0970	MTH 19-Jun-2001 LDG 0		9948	0	9948	6247
323002 RIGHT MAIN LANDING GEAR <i>323002A : R</i>	ACTUATOR ASSEMBLY 9912397-8	*CF		1541800-13 0973	MTH 19-Jun-2001 LDG 0		9948	0	9948	6247
323003	NG UPLOCK ACTUATOR *CF			6327504-7 86	MTH 19-Jun-2001		O/C			
323005 LEFT	MLG UPLOCK ACTUATOR *CF			6327504-6 114	MTH 19-Jun-2001		O/C			
323005 RIGHT	MLG UPLOCK ACTUATOR *CF			6327504-6 102	MTH 19-Jun-2001		O/C			
323006	HYD SHUTTLE VALVE *CF			95784 769	MTH 19-Jun-2001		O/C			
324001 LEFT	MAIN LANDING GEAR WHEEL 9912398-7	*CF		3-1527-2 1265	MTH 19-Jun-2001		O/C			
324001 RIGHT	MAIN LANDING GEAR WHEEL 9912398-7	*CF		3-1527-2 1224	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324002 NOSE	LANDING GEAR WHEEL ASSY 9914069-2	SGF		3-1418 5386P	MTH 04-Feb-2015 HRS 3194.9 LDG 2841		O/C			
324005 LEFT	MLG TIRE	KSNL		277K08-1 90842465	MTH 15-May-2019 HRS 4028.5 LDG 3557		O/C	0 0		
324005 RIGHT	MLG TIRE	KSNL		277K08-1 90832532	MTH 15-May-2019 HRS 4028.5 LDG 3557		O/C	0 0		
324007 NOSE	LANDING GEAR TIRE	KSNL		184F08-1 90882958	MTH 15-May-2019 HRS 4028.5 LDG 3557		O/C	0 0		
324008 LEFT <i>324007 : L</i>	SHUTTLE VALVE *CF			195-191-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324008 RIGHT	SHUTTLE VALVE *CF			195-191-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324016 LEFT MAIN LANDING GEAR	BRAKE ASSY 9912398-8	SGF		2-1559-3 0071	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		O/C			
324016 RIGHT MAIN LANDING GEAR	BRAKE ASSY 9912398-8	SGF		2-1559-3 0194	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		O/C			
324101	POWER BRAKE AND ANTISKID VALVE 9912374-4	SGF		38-747 454	MTH 04-Oct-2013 HRS 2749.6 LDG 2476		O/C	0 0 0		
324102 LEFT	ANTISKID TRANSDUCER ASSEMBLY 9912305-2	*CF		40-955 4793	MTH 19-Jun-2001		O/C			
324102 RIGHT	ANTISKID TRANSDUCER ASSEMBLY 9912305-2	*CF		40-955 5367	MTH 19-Jun-2001		O/C			
324103	BRAKE CONTROL BOX 9912305-6	SGF		42-707-1 516	MTH 08-Oct-2013 HRS 2758.6 LDG 2485		O/C			
324104 LEFT	BRAKE CYLINDER ASSEMBLY 9912366-1	*CF		95805 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324104 RIGHT	BRAKE CYLINDER ASSEMBLY 9912366-1	*CF		95805 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324104A LEFT	BRAKE CYLINDER ASSEMBLY 9912366-2	*CF		95805-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324104A RIGHT	BRAKE CYLINDER ASSEMBLY 9912366-2	*CF		95805-1 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324105	PARKING BRAKE VALVE 9912388-1	*CF		95853 0579A	MTH 19-Jun-2001		O/C			
324106	HYDRAULIC PUMP MOTOR *CF			MP50B1 1898	MTH 19-Jun-2001		O/C			
324107	ANTISKID ACCUMULATOR *CF			57C57663 0499	MTH 19-Jun-2001		O/C			
324108	HYDRAULIC PRESSURE SWITCH 9912373-1	*CF		GPP1250-29 0108553	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324109	BRAKE PRESSURE PUMP ASSY 9912364-2	*CF		640929 1364	MTH 19-Jun-2001		O/C			
324110	EMERGENCY BRAKE VALVE ASSY ICT			878208-05 V152	MTH 04-Apr-2012 HRS 2440.1 LDG 2246		O/C	0 0 0		
324111 LEFT	MLG UP & LOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324111 RIGHT	MLG UP & LOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324111	NLG UP & LOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
324112	PRESSURE ANTISKID SWITCH 9912374-6	*CF		38-747502 0614	MTH 19-Jun-2001		O/C			
325001	NOSE LANDING GEAR ASSEMBLY *CF			6342000-27 051	MTH 19-Jun-2001		O/C			
325002	NOSE STEERING BUNGEE ASSEMBLY *CF			5565624-19 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
326001 LEFT	M/G DOWN&LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
326001 RIGHT	M/G DOWN&LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
326002	N/G DOWN&LOCK SWITCH *CF			1EN118-6 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
326006	EMERGENCY GEAR BOTTLE KALN			40005320-2/9912368- 2 3764	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		288	217	30-Nov-2026	43 m 2 d
Manufacture Date: 29-Nov-2002										
326007	EMERGENCY GEAR GAUGE *CF			18225901 003503	MTH 19-Jun-2001		O/C			
330001 CENTER	PANEL LIGHTS DIMMER *CF			273-1 0047098	MTH 19-Jun-2001		O/C			
330001 LEFT	PANEL LIGHTS DIMMER *CF			273-1 0047092	MTH 19-Jun-2001		O/C			
330001 RIGHT	PANEL LIGHTS DIMMER *CF			273-1 0108124	MTH 19-Jun-2001		O/C			
330002	ELECTRICAL PANEL INVERTER *CF			EM2044-1 3255A	MTH 19-Jun-2001		O/C			
332001 L1	INDIRECT LIGHTING INVERTER *CF			6900113-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
332002 L2	INDIRECT LIGHTING INVERTER *CF			6900113-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
332003 L3	INDIRECT LIGHTING INVERTER *CF			6900113-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
332004 L4	INDIRECT LIGHTING INVERTER *CF			6900113-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
332005 R1	INDIRECT LIGHTING INVERTER *CF			6900113-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
332006 R2	INDIRECT LIGHTING INVERTER *CF			6900113-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
332007 R3	INDIRECT LIGHTING INVERTER *CF			6900113-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
332008 R4	INDIRECT LIGHTING INVERTER *CF			6900113-3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
334001	GROUND RECOGNITION LIGHT *CF			90033-13 012638	MTH 19-Jun-2001		O/C			
334003 LEFT	ANTI COLLISION POWER SUPPLY *CF		1	04-1502-1408 10902	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
334003 RIGHT	ANTI COLLISION POWER SUPPLY *CF		1	04-1502-1408 10739	MTH 19-Jun-2001		O/C			
334004 LEFT	HOUSING ASSY-LANDING LIGHT LAMP *CF			50033025-1 991	MTH 19-Jun-2001		O/C			
334004 RIGHT	HOUSING ASSY-LANDING LIGHT LAMP *CF			50033025-1 980	MTH 19-Jun-2001		O/C			
334005 LEFT	ANTI COLLISION LIGHT ASSY *CF		1	03-1302-0003 13199	MTH 19-Jun-2001		O/C			
334005 RIGHT	ANTI COLLISION LIGHT ASSY *CF		1	03-1302-0004 13231	MTH 19-Jun-2001		O/C			
334006 LEFT	EMERGENCY EXIT BATTERY PACK KICT			CBS28-1 3999M	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		O/C			
340551	FLIGHT STREAM 510 --			011-03595-00 SN-UNKNOWN	MTH 15-Jan-2019 HRS 4000.5 LDG 3531		O/C	0 0 0		
341001 RIGHT	AIRSPEED INDICATOR 9912446-4	KICT		37277-525 1113	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		O/C			
341001	AOA COMPUTER	*CF		C12406-3 183	MTH 19-Jun-2001		O/C			
341002	AOA CONTROLLER	*CF	A	C12421-1 530	MTH 19-Jun-2001		O/C			
341008	AOA INDICATOR			C12405-1 7871	MTH 28-Jul-2006 HRS 1206		O/C	105		
341009	AOA SENSOR	*CF		C12417-2 563	MTH 19-Jun-2001		O/C			
341010 AFT	RADIO ALTIMETER ANTENNA *CF			S67-2002 21226	MTH 19-Jun-2001		O/C			
341010 FORWARD	RADIO ALTIMETER ANTENNA *CF			S67-2002 21227	MTH 19-Jun-2001		O/C			
341020 RIGHT	ADC/ALT UNIT AM-250	MCO		70251N02D04 04051427D	MTH 02-Dec-2004 HRS 568		O/C	0		
341029	MARKER BEACON INDICATOR *CF		1	066-01044-0001 1454	MTH 19-Jun-2001		O/C			
341031	TEMPERATURE PROBE SENSOR *CF			0129G A37373	MTH 19-Jun-2001		O/C			
341101	IAPS ICC 3001 CARD *CF			822-1459-001 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
341102 NO. 1	IO PROCESSOR CARD *CF			822-1130-101 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
341102 NO. 2	IO PROCESSOR CARD *CF			822-1130-101 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
341103 NO. 1	CONFIGURATION STRAPPING UNIT *CF			822-1363-002 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
341103 NO. 2	CONFIGURATION STRAPPING UNIT *CF			822-1363-002 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
342001	MAGNETIC COMPASS C2400-L4V2W-5B	SGF		C660501-0301 NSN	MTH 20-Nov-2012 HRS 2507.4 LDG 2303		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342004 RIGHT	ATTITUDE DIRECTOR INDICATOR ICT	D		2802-01-1 156	MTH 04-Apr-2012 HRS 2440.1 LDG 2246		O/C			
342009	ENVIRONMENTAL CONTROL IEC	*CF	2	822-1167-001 DJGT	MTH 19-Jun-2001		O/C			
342012 STANDBY	AIRSPEED ALTIMETER *CF		11	WL102AMS6 AN119	MTH 19-Jun-2001		O/C			
342014	COURSE & HEADING PANEL CHP-3000	*CF		822-1279-002 DK5B	MTH 19-Jun-2001		O/C			
342015 LEFT	AHRS COMPUTER AHC-3000	SGF	1	822-1110-001 1044B	MTH 24-Jul-2013 HRS 2690.2 LDG 2432		O/C	0 0 0		
342015 RIGHT	AHRS COMPUTER AHC-3000	*CF	1	822-1110-001 DLCN	MTH 19-Jun-2001		O/C			
342016 LEFT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-001 CT2C	MTH 19-Jun-2001		O/C			
342016 RIGHT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-001 DW2H	MTH 19-Jun-2001		O/C			
342021 RIGHT	VERTICAL SPEED INDICATOR KICT			C661006-0101 355723	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		O/C	0 0 0		
342042 RIGHT	FLIGHT DIRECTOR MODE SELECTOR MSP-85	*CF	10	622-6209-019 DP75	MTH 19-Jun-2001		O/C			
342044 LEFT	FLIGHT GUIDANCE COMPUTER SMF			822-1108-118 D29V	MTH 09-Jun-2003 HRS 92		O/C	0		
342044 RIGHT	FLIGHT GUIDANCE COMPUTER SMF			822-1108-118 DL5B	MTH 09-Jun-2003 HRS 92		O/C	0		
342046	HORIZONTAL SITUATION INDICATOR SGF			2855-01-1 024	MTH 10-Jan-2014 HRS 2816.1 LDG 2528		O/C			
342050 LEFT	FLUX DETECTOR *CF			822-1193-001 22012	MTH 19-Jun-2001		O/C			
342050 RIGHT	FLUX DETECTOR *CF			822-1193-001 25039	MTH 19-Jun-2001		O/C			
342051 STANDBY	HORIZONTAL SITUATION INDICATOR (S3100-303) MOD G & ON	ICT D		2855-01-1 JP3122	MTH 17-Jul-2012 HRS 2441.8 LDG 2248		O/C			
342054 CENTER	FLIGHT ADAPTIVE DISPLAY MFD UNIT SGF			822-1084-110 20L8	MTH 12-Jul-2016 HRS 3654 LDG 3246 ACH 2143.9		O/C			
342054 LEFT	FLIGHT ADAPTIVE DISPLAY UNIT SGF			822-1084-110 168	MTH 12-Jul-2016 HRS 3654 LDG 3246 ACH 2143.9		O/C			
342063	STANDBY JET GYRO AI-300AE	SGF	0	501-1568-56 3043	MTH 12-Jun-2013 HRS 2668.8 LDG 2415		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342064	STANDBY GYRO POWER SUPPLY KALN			501-1682-01 1031	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		O/C			
342068 RIGHT	CONTROL DISPLAY PANEL DCP-3000	*CF	B	822-1134-102 FB7M	MTH 19-Jun-2001		O/C			
344001	ANTENNA GLIDESLOPE COUPLER *CF			82-70-01 1152	MTH 19-Jun-2001		O/C			
344005	RADAR TRANSCEIVER *CF		66	822-1050-004 DLDW	MTH 19-Jun-2001		O/C			
344007 CENTER	FMS CONFIGURATION MODULE KMC-100	*CF		071-00073-5000 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
344023 NO. 1	DUAL NAVIGATION CONVERTER KN-40	*CF	6	066-01130-0701 11931	MTH 19-Jun-2001		O/C			
344024	RADIO ALTIMETER INDICATOR ICT		10	622-2855-011 FWDT	MTH 27-Jun-2001 HRS 8		O/C	0		
344025	RADIO ALTIMETER CONVERTER RAC-870	*CF		622-7209-002 D75K	MTH 19-Jun-2001		O/C			
345001 FORWARD	DME #1 ANTENNA *CF			56-80-01 8022	MTH 19-Jun-2001		O/C			
345002 NO. 2	DME RECEIVER/TRANSMITTER KN-63	*CF	6	066-01070-0001 15782	MTH 19-Jun-2001		O/C			
345003 LEFT	DME INDICATOR KDI-574	*CF		066-01069-0014 72807	MTH 19-Jun-2001		O/C			
345004 NO. 1	TRANSPONDER ANTENNA *CF			DMNI50-2-2 79689	MTH 19-Jun-2001		O/C			
345004 NO. 2	TRANSPONDER ANTENNA *CF			DMNI50-2-2 79698	MTH 19-Jun-2001		O/C			
345005	MARKER BEACON ANTENNA *CF			31-10-01 3740	MTH 19-Jun-2001		O/C			
345006	GLIDESLOPE ANTENNA *CF			44-70-01 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
345008 LEFT	DME 1 CONVERTER KDA-689	*CF	1	071-01227-0001 10781	MTH 19-Jun-2001		O/C			
345011 NO. 1	ADF RECEIVER KR-87	ICT		066-01072-0006 75836	MTH 16-Apr-2012 HRS 2440.8 LDG 2247		O/C	2440.8 2247		
345012 NO. 1	ADF ANTENNA KA-44B	*CF	2	071-01234-0000 75698	MTH 19-Jun-2001		O/C			
345020 BOTTOM	VHF NAV 2 RECEIVER S3100-33/KN-53	*CF	11	066-01067-0004 71977	MTH 19-Jun-2001		O/C			
345020 TOP	VHF NAV 1 RECEIVER S3100-33/KN-53	ICT	11	066-01067-0004 71907	MTH 04-Apr-2012 HRS 2440.1 LDG 2246		O/C	2440.1 2246		
345022 LEFT	NAVIGATION ANTENNA C598505-0303	*CF		22-37-101 2629	MTH 19-Jun-2001		O/C			
345022 RIGHT	NAVIGATION ANTENNA C598505-0303	*CF		22-37-101 2628	MTH 19-Jun-2001		O/C			
345034 NO. 1	TRANSPONDER *CF	UNK	5	011-03303-00 3EH022843	MTH 15-Jan-2019 HRS 4000.5 LDG 3531		O/C			
345034 NO. 2	TRANSPONDER *CF	UNK	5	011-03301-00 3EF021231	MTH 15-Jan-2019 HRS 4000.5 LDG 3531		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345039 RIGHT	GPS 2 ANTENNA			013-00244-00 151007	MTH 11-Sep-2018 HRS 3979.8 LDG 3519		O/C			
345039	GPS 1 ANTENNA GA36			013-00244-00 151028	MTH 11-Sep-2018 HRS 3979.8 LDG 3519		O/C			
345040	NAV DATA BASE GPS KLN-90	*CF		071-01523-0102 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
345053A NO. 1	GTN-750 GPS/COMM/NAV UNIT			011-02282-50 12A210968	MTH 11-Sep-2018 HRS 3979.8 LDG 3519		O/C	0 0 0		
345053B NO. 2	GTN-650 GPS/COMM/NAV UNIT			011-02256-50 128210226	MTH 11-Sep-2018 HRS 3979.8 LDG 3519		O/C	0 0 0		
345054	GPS CONVERTER			1201-4000-04 1809135	MTH 11-Sep-2018 HRS 3979.8 LDG 3519		O/C	0 0 0		
345201	MD-41 ANNUNCIATOR			MD41-1038 ML8-11965	MTH 11-Sep-2018 HRS 3979.8 LDG 3519		O/C	0 0 0		
346001 NO. 1	GPS RECEIVER S3100-201/KLN-900	SGF	3	066-04034-0204 3419	MTH 12-Jun-2013 HRS 2668.8 LDG 2415		O/C	0 0 0		
346009 LEFT	AIR DATA COMPUTER ADC-3000	KALN	2	822-1109-002 2VC6R	MTH 22-Jan-2021 HRS 4152.4 LDG 3633		O/C	0 0		
350006	OXYGEN BOTTLE DOT-E 8162 (DOT3FC)			176274-22 ALT280-5623/1438	MTH 01-Feb-2021 HRS 4152.4 LDG 3633		180		30-Nov-2030	91 m 2 d
Manufacture Date: 30-Nov-2015										
350007	OXYGEN PRESSURE GAGE MD-97	*CF		C668512-0101 C21586	MTH 19-Jun-2001		O/C			
351002 COPILOT	OXYGEN MASK 9914067-41	SGF		MC10-16-101 SE6447	MTH 18-May-2017 HRS 3835.6 LDG 3390 ACH 2221.9		72	0	31-May-2023	1 m 3 d
351002 PILOT	OXYGEN MASK 9914067-41	KALN		MC10-16-101 100775	MTH 16-Jan-2018 HRS 3944.8 LDG 3500 ACH 2305.1		72	0	31-Jan-2024	9 m 3 d
351004 LEFT	ALTITUDE PRESSURE SWITCH 9912057-5	*CF		P24031 2278	MTH 19-Jun-2001		O/C			
351008	OXYGEN 3 POSITION VALVE 9912057-21	*CF		110081-06 0639	MTH 19-Jun-2001		O/C			
361001 LEFT	TEMPERATURE SENSOR 9912057-21	*CF		27431501-05 12AT143	MTH 19-Jun-2001		O/C			
361001 RIGHT	TEMPERATURE SENSOR 9912057-21	*CF		27431501-05 9AT99	MTH 19-Jun-2001		O/C			
361002 LEFT	B/A PRECOOLER ASSEMBLY 9914402-6	SGF		8161-5 S4883T0782	MTH 23-Mar-2017 HRS 3805.6 LDG 3368 ACH 2212.3		3200	0	7005.6	2751.8



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361002 RIGHT	B/A PRECOOLER ASSEMBLY 9914402-6	SGF		8161-5 S4883T0631	MTH 23-Mar-2017 HRS 3805.6 LDG 3368 ACH 2212.3		3200	0	7005.6	2751.8
361004 LEFT	PNEUMATIC SHUTOFF VALVE ASSY *CF			2601-21 0283	MTH 19-Jun-2001		O/C			
361004 RIGHT	PNEUMATIC SHUTOFF VALVE ASSY *CF			2601-21 0233	MTH 19-Jun-2001		O/C			
361006	PRESSURE BLEED AIR REGULATOR 9912043-4	*CF		1H75-16 1AU6	MTH 19-Jun-2001		O/C			
361007 LEFT	OVER TEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 2464	MTH 19-Jun-2001		O/C			
361007 RIGHT	OVER TEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 2525	MTH 19-Jun-2001		O/C			
361007	DOOR SEAL CONTROL VALVE *CF			MJV3 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
361008 LEFT	PRECOOLER DOOR VALVE *CF			5060-00-01 1727	MTH 19-Jun-2001		O/C			
361008 RIGHT	PRECOOLER DOOR VALVE *CF			5060-00-01 1742	MTH 19-Jun-2001		O/C			
361009 LEFT	CHECK VALVE *CF			5253-00-1 0315	MTH 19-Jun-2001		O/C			
361009 RIGHT	CHECK VALVE	ICT		5253-00-1 0944	MTH 16-Oct-2012 HRS 2478.4 LDG 2280		O/C	0 0 0		
361010 LEFT	CHECK VALVE *CF			1553-00-18 2489	MTH 19-Jun-2001		O/C			
361010 RIGHT	CHECK VALVE *CF			1553-00-18 2486	MTH 19-Jun-2001		O/C			
361011 LEFT	PRECOOLER ACTUATOR *CF			1H126-1 2AU6	MTH 19-Jun-2001		O/C			
361012 RIGHT	PRECOOLER ACTUATOR *CF			1H126-1 2AU12	MTH 19-Jun-2001		O/C			
521000	CABIN ENTRY DOOR			PN SN-UNKNOWN	MTH 19-Jun-2001		O/C	0		
522001	DOOR INFLATABLE SEAL SGF			9912075-4 NSN	MTH 17-Mar-2015 HRS 3246.5 LDG 2884		O/C	0 0		
522002	SECONDARY SEAL	MCO		R860081 NSN	MTH 19-Jun-2008 HRS 1848		O/C	0		
522003	ESCAPE HATCH SEAL *CF			R441236 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
522004	PRESSURE SWITCH *CF			P18M-30 2523	MTH 19-Jun-2001		O/C			
522005	EMERGENCY ESCAPE HATCH			PN SN-UNKNOWN	MTH 19-Jun-2001		H/T H/T	0		
531000 LEFT	TRUNNION SUPPORT FITTING *CF			5513056-5 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		22500	0	22500	18799
531000 RIGHT	TRUNNION SUPPORT FITTING *CF			5513056-6 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		22500	0	22500	18799
531001	ACTUATOR SUPPORT FITTING *CF			6511105-1 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		22500	0	22500	18799
531201	RADOME ASSEMBLY *CF			6313101-47 SN-UNKNOWN	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
561001 LEFT	WINDSHIELD ASSY, (LH)	ICT		9912064-15 2883	MTH 17-Jul-2012 HRS 2441.8 LDG 2248		O/C			
561001 RIGHT	WINDSHIELD ASSY, (RH)	UNK		E149000-102 2458	MTH 16-Jan-2012 HRS 2440.1 LDG 2246		O/C	0 0 0		
561002 L1	CABIN DOOR WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
561002 L2	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
561002 L3	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
561002 L4	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
561002 R1	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
561002 R2	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
561002 R3	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
561002 R4	CABIN WINDOW	*CF		161100-03 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
561003 PILOT	SIDE WINDOW	ICT		6311065-27 0525	MTH 20-Jan-2012 HRS 2338.9 LDG 2133		O/C		2338.9 2133	
561004 COPILOT	SIDE WINDOW	ICT		6311065-26 02220101	MTH 20-Jan-2012 HRS 2338.9 LDG 2133		O/C		2338.9 2133	
571000 LEFT AFT <i>571000A : L</i>	TRUNNION ATTACH FITTING	*CF		6322070-17 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
571000 RIGHT AFT <i>571000A : R</i>	TRUNNION ATTACH FITTING	*CF		6322070-16 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
571001 LEFT FORWARD <i>571001A : L</i>	TRUNNION ATTACH FITTING	*CF		6322060-15 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
571001 RIGHT FORWARD <i>571001A : R</i>	TRUNNION ATTACH FITTING	*CF		6322060-16 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
571002 LEFT <i>571002A : L</i>	SIDE BRACE FITTING	*CF		6322080-21 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
571002 RIGHT <i>571002A : R</i>	SIDE BRACE FITTING	*CF		6322080-20 SN-UNKNOWN	MTH 19-Jun-2001 LDG 0		23400	0	23400	19699
712001 LEFT ENGINE AFT	ISOLATOR MOUNT	*CF		LM601SA4 SN-UNKNOWN	MTH 19-Jun-2001 HRS 0		CSI CSI	0	5024.2	770.4
712001 LEFT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT	*CF		LM601SA5 SN-UNKNOWN	MTH 19-Jun-2001 HRS 0		CSI CSI	0	5024.2	770.4
712001 LEFT ENGINE FORWARD TOP	ISOLATOR MOUNT	*CF		LM601SA5 SN-UNKNOWN	MTH 19-Jun-2001 HRS 0		CSI CSI	0	5024.2	770.4



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
712001 RIGHT ENGINE AFT	ISOLATOR MOUNT 9912410-2	*CF		LM601SA4 SN-UNKNOWN	MTH 19-Jun-2001 HRS 0		CSI CSI	0	5000	746.2
712001 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912410-3	*CF		LM601SA5 SN-UNKNOWN	MTH 19-Jun-2001 HRS 0		CSI CSI	0	5000	746.2
712001 RIGHT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912410-3	*CF		LM601SA5 SN-UNKNOWN	MTH 19-Jun-2001 HRS 0		CSI CSI	0	5000	746.2
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE	MCO		45700-104 1901	MTH 19-Jun-2008 HRS 1848		E/C	1823		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	*CF		45700-104 1902	MTH 19-Jun-2001		E/C			
720007 E1	1ST LP TURBINE NOZZLE	MCO		57375 AU20080	MTH 19-Jun-2008 HRS 1848		O/C	37		
720007 E2	1ST LP TURBINE NOZZLE	SWF		57375 GD771A	MTH 17-Apr-2008 HRS 1786		O/C	0		
723001 E1	FAN ROTOR	MCO		59070 AU00670	MTH 19-Jun-2008 HRS 1848.2 LDG 1788		16500	1768	16520	12819
723001 E2	FAN ROTOR	*CF		59070 AU00671	MTH 19-Jun-2001 LDG 0		16500	0	16500	12799
723010 E1	HP COMPRESSOR ROTOR	MCO		60442 LC2241	MTH 19-Jun-2008 HRS 1848.2 LDG 1788		8000	1776	8012	4311
723010 E2	HP COMPRESSOR ROTOR	*CF		60442 LC2236	MTH 19-Jun-2001 LDG 0		8000	0	8000	4299
723015 E1	IP COMPRESSOR ROTOR	MCO		66032 HW13745	MTH 19-Jun-2008 HRS 1848.2 LDG 1788		10000	1698	10090	6389
723015 E2	IP COMPRESSOR ROTOR	SMF		66032 HW13722	MTH 22-Aug-2002 HRS 75 LDG 70		10000	0	10070	6369
723022 E1	DIFFUSER CASE ASSEMBLY	MCO		59906 AU01172	MTH 19-Jun-2008 HRS 1848		O/C	1823		
723022 E2	DIFFUSER CASE ASSEMBLY	*CF		59906 AU01106	MTH 19-Jun-2001		O/C			
723061 E1	HIGH PRESSURE SHAFT	MCO		64711 AU00273	MTH 19-Jun-2008 HRS 1848		O/C	1823		
723061 E2	HIGH PRESSURE SHAFT	*CF		64711 AU00299	MTH 19-Jun-2001		O/C			
723092 E1	COMPLETE LP SHAFT ASSEMBLY 40	MCO		50865 RXISN6792	MTH 19-Jun-2008 HRS 1848		O/C	1823		
723092 E2	COMPLETE LP SHAFT ASSEMBLY 40	*CF		50865 RXISN6789	MTH 19-Jun-2001		O/C			
723149 E1	HP COMPRESSOR COVER ASSY 260	MCO		59582 AU01391	MTH 19-Jun-2008 HRS 1848		O/C	1823		
723149 E2	HP COMPRESSOR COVER ASSY 260	*CF		59582 AU01394	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
724035 E1	HP TURBINE ROTOR ASSEMBLY MCO			65442 RRL1116	MTH 19-Jun-2008 HRS 1848		O/C	1823		
724035 E2	HP TURBINE ROTOR ASSEMBLY *CF			65442 RRL1115	MTH 19-Jun-2001		O/C			
724040 E1	REAR FUEL SLINGER SEAL ASSEMBLY 280 MCO			55608 AU02283	MTH 19-Jun-2008 HRS 1848		O/C	37		
724040 E2	REAR FUEL SLINGER SEAL ASSEMBLY 280 SWF			55608 AU02418	MTH 17-Apr-2008 HRS 1786		O/C	1767		
725010 E1	HP TURBINE DISK MCO			59494 RRL7S00415	MTH 19-Jun-2008 HRS 1848.2 LDG 1788		8000 8000	1823 1776	8025.2 8012	3771.4 4311
725010 E2	HP TURBINE DISK *CF			59494 RRL7S00425	MTH 19-Jun-2001 HRS 0 LDG 0		8000 8000	0 0	8000 8000	3746.2 4299
725020 E1	1ST LP TURBINE DISK 411 MCO			50255 RRL7S01426	MTH 19-Jun-2008 HRS 1848.2 LDG 1788		14700	1776	14712	11011
725020 E2	1ST LP TURBINE DISK 411 *CF			50255 RRL7S01310	MTH 19-Jun-2001 LDG 0		14700	0	14700	10999
725030 E1	2ND LP TURBINE DISK 551 MCO			50792 RRL7S01354	MTH 19-Jun-2008 HRS 1848.2 LDG 1788		13500	1776	13512	9811
725030 E2	2ND LP TURBINE DISK 551 *CF			50792 RRL7S01338	MTH 19-Jun-2001 LDG 0		13500	0	13500	9799
726011 E1	ACCESSORY DRIVE GEARBOX ASSEMBLY MCO			60570 WL02435	MTH 19-Jun-2008 HRS 1848		O/C	1823		
726011 E2	ACCESSORY DRIVE GEARBOX ASSEMBLY *CF			60570 WL02439	MTH 19-Jun-2001		O/C			
730001 LEFT ENGINE	FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 4933	MTH 19-Jun-2001		O/C			
730001 RIGHT ENGINE	FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 4903	MTH 19-Jun-2001		O/C			
732002	SYNCHRONIZER CONTROLLER *CF			213693 13017413	MTH 19-Jun-2001		O/C			
732003	ENGINE SYNCHRONIZER ACTUATOR *CF			5485-066 12412919	MTH 19-Jun-2001		O/C			
733001 LEFT ENGINE	FUEL FLOW TRANSMITTER SGF			9912417-1 1437	MTH 18-Jun-2015 HRS 3341.8 LDG 2959		O/C			
733001 RIGHT ENGINE	FUEL FLOW TRANSMITTER 9912417-1 *CF			1573-4 1046	MTH 19-Jun-2001		O/C			
730002 E1	FUEL NOZZLE ASSEMBLY 115 KICT			50817 BCC-00012953	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		O/C			
730002 E2	FUEL NOZZLE ASSEMBLY 115 KICT			50817 BCC-00014196	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		O/C			
731001 E1	FUEL PUMP 640 MCO			54904 YYK1202	MTH 19-Jun-2008 HRS 1848.2		6000	1823	6025.2	1771.4
731001 E2	FUEL PUMP 640 *CF			54904 YYK1203	MTH 19-Jun-2001 HRS 0		6000	0	6000	1746.2



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
732090 E1	START NOZZLE CONTROL VALVE 625	MCO		50803 RF12412994	MTH 19-Jun-2008 HRS 1848.2		5000	1823	5025.2	771.4
732090 E2	START NOZZLE CONTROL VALVE 625	*CF		50803 RF12412993	MTH 19-Jun-2001 HRS 0		5000	0	5000	746.2
732301 E1	ELEC FUEL FILTER INDICATOR MCO			57847 GE0832	MTH 19-Jun-2008 HRS 1848		O/C	1823		
732301 E2	ELEC FUEL FILTER INDICATOR *CF			57847 GE0826	MTH 19-Jun-2001		O/C			
732401 E1	FUEL CONTROL (HMU) UNIT 630	MCO		55629 RF13004642	MTH 19-Jun-2008 HRS 1848.2		6000	1823	6025.2	1771.4
732401 E2	FUEL CONTROL (HMU) UNIT 630	*CF		55629 RF13005287	MTH 19-Jun-2001 HRS 0		6000	0	6000	1746.2
741010 E1 INBOARD	IGNITION EXCITER MCO			56635 CK0100077	MTH 19-Jun-2008 HRS 1848		O/C	1823		
741010 E2 INBOARD	IGNITION EXCITER *CF			56635 CK0100113	MTH 19-Jun-2001		O/C			
741020 E1 OUTBOARD	IGNITION EXCITER MCO			56635 CK0100115	MTH 19-Jun-2008 HRS 1848		O/C	1823		
741020 E2 OUTBOARD	IGNITION EXCITER *CF			56635 CK0100182	MTH 19-Jun-2001		O/C			
742001 E1	SHORT IGNITOR LEAD MCO			50852 NSN	MTH 19-Jun-2008 HRS 1848		O/C	1823		
742001 E2	SHORT IGNITOR LEAD *CF			50852 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
742002 E1	LONG IGNITOR LEAD MCO			50853 NSN	MTH 19-Jun-2008 HRS 1848		O/C	1823		
742002 E2	LONG IGNITOR LEAD *CF			50853 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
742201 E1 INBOARD	IGNITOR KICT			68032 CK-1905804	MTH 01-Dec-2022 HRS 4247.2 LDG 3701		O/C			
742201 E1 OUTBOARD	IGNITOR KICT			68032 CK-1903548	MTH 01-Dec-2022 HRS 4247.2 LDG 3701		O/C			
742201 E2 INBOARD	IGNITOR KICT			68032 CK-1802099	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		O/C			
742201 E2 OUTBOARD	IGNITOR KICT			68032 CK-0600937	MTH 01-Dec-2022 HRS 4248.5 LDG 3701		O/C			
771003 STANDBY	N1 INDICATOR SGF			10645N01R02 0230A	MTH 23-Aug-2016 HRS 3664.4 LDG 3256 ACH 2154.4		O/C			
771004	COMPUTER-N1 SMF			C-13232-1 537	MTH 09-Jun-2003 HRS 92		O/C	141		
774002 LEFT	FWD DCU CONCENTRATOR UNIT DCU-3010	*CF		822-1278-001 DVVV	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
774002 RIGHT	FWD DCU CONCENTRATOR UNIT DCU-3010	*CF		822-1278-001 DN3K	MTH 19-Jun-2001		O/C			
774002A LEFT	AFT CONCENTRATOR UNIT DCU-3010	*CF		822-1278-001 DVVK	MTH 19-Jun-2001		O/C			
774002A RIGHT	AFT CONCENTRATOR UNIT DCU-3010	*CF		822-1278-001 DN3N	MTH 19-Jun-2001		O/C			
771005 E1	N1 DUAL MAGNETIC SPEED SENSOR 740	MCO		50867 YYV920	MTH 19-Jun-2008 HRS 1848		O/C		1823	
771005 E2	N1 DUAL MAGNETIC SPEED SENSOR 740	*CF		50867 YYV931	MTH 19-Jun-2001		O/C			
771015 E1	N2 DUAL MAGNETIC SPEED SENSOR 750	MCO		50866 YYV804	MTH 19-Jun-2008 HRS 1848		O/C		1823	
771015 E2	N2 DUAL MAGNETIC SPEED SENSOR 750	*CF		50866 YYV696	MTH 19-Jun-2001		O/C			
772001 E1 NO. 1	ITT PROBE	MCO		62141 YYF004857	MTH 19-Jun-2008 HRS 1848		O/C		1823	
772001 E1 NO. 2	ITT PROBE	MCO		62141 SN-UNKNOWN	MTH 19-Jun-2008 HRS 1848		O/C		2129	
772001 E1 NO. 3	ITT PROBE	MCO		62141 YYF004859	MTH 19-Jun-2008 HRS 1848		O/C		1823	
772001 E1 NO. 4	ITT PROBE	MCO		62141 YYF004860	MTH 19-Jun-2008 HRS 1848		O/C		1823	
772001 E1 NO. 5	ITT PROBE	MCO		62141 YYF004861	MTH 19-Jun-2008 HRS 1848		O/C		1823	
772001 E1 NO. 6	ITT PROBE	MCO		62141 YYF004862	MTH 19-Jun-2008 HRS 1848		O/C		1823	
772001 E2 NO. 1	ITT PROBE	*CF		62141 YYF004923	MTH 19-Jun-2001		O/C			
772001 E2 NO. 2	ITT PROBE	*CF		62141 YYF004924	MTH 19-Jun-2001		O/C			
772001 E2 NO. 3	ITT PROBE	*CF		62141 YYF004925	MTH 19-Jun-2001		O/C			
772001 E2 NO. 4	ITT PROBE	*CF		62141 YYF004926	MTH 19-Jun-2001		O/C			
772001 E2 NO. 5	ITT PROBE	*CF		62141 YYF004927	MTH 19-Jun-2001		O/C			
772001 E2 NO. 6	ITT PROBE	*CF		62141 YYF004928	MTH 19-Jun-2001		O/C			
783001 LEFT	T/A SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
783001 RIGHT	T/A SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
783002 LEFT	T/A PADDLE ASSY	*CF		6354051-79 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
783002 RIGHT	T/A PADDLE ASSY	*CF		6354051-79 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
783003 LEFT	ATTENUATOR ACTUATOR	*CF		6317105-13 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
783003 RIGHT	ATTENUATOR ACTUATOR	*CF		6317105-13 00227	MTH 19-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
783005 LEFT	THRUST ATTENUATOR BELLCRANK *CF			6354051-103 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
783005 RIGHT	THRUST ATTENUATOR BELLCRANK *CF			6354051-104 SN-UNKNOWN	MTH 19-Jun-2001		O/C			
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER *CF			MS28034-3 84825	MTH 19-Jun-2001		O/C			
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER *CF			MS28034-3 85091	MTH 19-Jun-2001		O/C			
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER *CF			APTE304-1000-200G 65392320	MTH 19-Jun-2001		O/C			
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER *CF			APTE304-1000-200G 65392349	MTH 19-Jun-2001		O/C			
793006 LEFT ENGINE	OIL PRESSURE SWITCH 9912178-4 *CF			S1103P89-3 1108	MTH 19-Jun-2001		O/C			
793006 RIGHT ENGINE	OIL PRESSURE SWITCH 9912178-4 *CF			S1103P89-3 1092	MTH 19-Jun-2001		O/C			
792201 E1	LUBE OIL COOLER	MCO		59866 PP0485	MTH 19-Jun-2008 HRS 1848		O/C		1823	
792201 E2	LUBE OIL COOLER *CF			59866 PP0486	MTH 19-Jun-2001		O/C			
792401 E1	LUBE AND SCAVENGE PUMP MCO			60689 WL01568	MTH 19-Jun-2008 HRS 1848.2		5000	1823	5025.2	771.4
792401 E2	LUBE AND SCAVENGE PUMP *CF			60689 WL01570	MTH 19-Jun-2001 HRS 0		5000	0	5000	746.2
801101 LEFT ENGINE	STARTER/GENERATOR SGF			9912125-2 5677XL2	MTH 25-Aug-2015 HRS 3435 LDG 3036		1000	0	4435	181.2
801101 RIGHT ENGINE	STARTER/GENERATOR SGF			9912125-2 2613XL2	MTH 25-Aug-2015 HRS 3435 LDG 3036		1000	0	4435	181.2



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	MOC :									
SL 525-99-02 R05	CESCOM PRICES (THIS SL CANCELS SL525-99-02 R4 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 525-99-05	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 525-99-06	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 525-03-01 R01	SUPPLEMENTAL TYPE CERTIFICATE (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)			INFORMATIONAL			-			
	MOC :									
SL 525-99-10	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SL 525-05-03 R01 <i>05SL-03 : 525R1</i>	NEW 525 TASK BASED INSPECTION PROGRAM	AFF		MANDATORY	DAYS 01-May-2010 HRS 2263.6 LDG 2071		DUE DUE DUE DUE			Complete
	MOC : COMPLIED WITH									
SL 525-05-05	PRECOOLER LIFE LIMIT	SGF		INFORMATIONAL	MTH 23-Mar-2017 HRS 3805.6 LDG 3368 ACH 2212.3		-			Complete
	MOC : COMPLIED WITH - C/W SL525-05-05 IAW CESSNA SL525-05-05 INSTRUCTIONS.									
SB FJ44-05-002 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R05-CN E1	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									
SB FJ44-05-002 R05-CN E2	SUPERSEDED - UNSERVICEABLE PARTS - NOTIFICATION (THIS SERVICE DOCUMENT HAS BEEN SUPERSEDED BY WIPSID-05-1000)			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-05-002 R05 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R05 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
MOC :										
PSID WI-05-1000 R04 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
PSID WI-05-1000 R04 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SL WI-05-1009-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1009-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1009 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1009 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1020 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1020 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										
SL WI-05-1021-CN E1	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1021-CN E2	CANCELED-TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-05-1021 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-05-1021 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SL WI-05-1022 E1	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SL WI-05-1022 E2	TIME LIMITS/MAINTENANCE CHECKS - UNSERVICEABLE PARTS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SL WI-05-1092-CN E1	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED						
	MOC :								
SL WI-05-1092-CN E2	CANCELED - TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL		CANCELLED						
	MOC :								
SL WI-05-1092 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SL WI-05-1092 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SL WI-05-1149 E1	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SL WI-05-1149 E2	TIME LIMITS/MAINTENANCE CHECKS - SCHEDULED MAINTENANCE CHECKS - REVISION TO LINE MAINTENANCE MANUAL								
	MOC :								
SB 525-11-10 <i>11SB-10</i>	AIRSPPEED AND OPERATIONAL LIMITS PLACARD REPLACEMENT	BFI	RECOMMENDED	MTH 10-Jan-2002 HRS 44					Complete
	MOC :								
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS								
			INFORMATIONAL						
	MOC :								
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS								
			INFORMATIONAL						
	MOC :								
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS								
			INFORMATIONAL						
	MOC :								
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH					
			RECOMMENDED						
	MOC :								
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL								
			INFORMATIONAL						
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL		INFORMATIONAL			-			
	MOC :								
SL 525-20-01 R18	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL		INFORMATIONAL			A/R			
	MOC :								
SL 525-20-06	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL		INFORMATIONAL			-			
	MOC :								
SB 525-21-16 R02 21SB-16 : 525R2	CABIN PRESSURE BUMPS DURING ENGINE STARTS		MTH DISCRETIONARY			A/R			
	MOC : - SERVICE BULLETIN ON HOLD.								
SB 525-21-17 R02	FORWARD EVAPORATOR RELAY INSTALLATION		OPTIONAL			-			
	MOC :								
SB 525-21-17 R03	FORWARD EVAPORATOR REPLAY INSTALLATION		MTH SGF OPTIONAL	30-Apr-2015 3287.3 2912		-			Complete
	MOC : COMPLIED WITH - C/W SB525-21-17 REV 3 IAW CESSNA CITATION 525 SB525-21-17 INSTRUCTIONS, OPS CHECK OK.								
SB 525-21-17 21SB-17	FORWARD EVAPORATOR RELAY INSTALLATION		MTH OPTIONAL			-			
	MOC :								
SB 525-21-19 21SB-19	TEMPERATURE SENSOR RELOCATION		OPTIONAL MTH			A/R			
	MOC :								
SB 525-21-20 R01	AIR CONDITIONING - BAROMETRIC PRESSURE SWITCH INSTALLATION		OPTIONAL			-			
	MOC :								
SB 525-21-20	BAROMETRIC PRESSURE SWITCH INSTALLATION		OPTIONAL			-			
	MOC :								
ASL 525-21-01 R01 21SLA01 : 525R1	AIR CONDITIONING - AIR CONDITIONING GROUND CABLE INSPECTION	BFI	MANDATORY	MTH HRS	04-Jan-2002 44	-			Complete
	MOC : COMPLIED WITH								
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT		INFORMATIONAL			-			
	MOC :								
SB 525-23-08 23SB-08	ALLIEDSIGNAL 8.33 KHZ COMMUNICATION RADIO INSTALLATION	ICT	OPTIONAL	MTH HRS	19-Jun-2001 7	-			Complete
	MOC : COMPLIED WITH								
SB 525-23-09 23SB-09	AERO-M ANTENNA NON-MAGNETIC SCREW REPLACEMENT	SMF	RECOMMENDED	MTH HRS	26-Aug-2002 75	-			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE								
SB 525-23-11 23SB-11	GARMIN RADIO MODIFICATION		RECOMMENDED	MTH HRS	01-Jul-2004 421	-			Complete
	MOC : COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-23-12 23SB-12	HONEYWELL KY-196A/KY-196B DUAL VHF COMMUNICATION SYSTEM UPGRADE	SMF		RECOMMENDED	MTH 09-Jun-2003 HRS 92		-			Complete
	MOC : COMPLIED WITH									
SB 525-23-13 23SB-13	GARMIN RADIO REPLACEMENT			OPTIONAL	MTH		-			
	MOC :									
SL 525-23-07 R01 23SL-07 : 525R1	TRANSMITTAL OF GARMIN SERVICE BULLETIN 0218, NEW SOFTWARE VERSION 3.00 (MAIN) FOR 400/500 SERIES UNITS AND 3.00 (GPS) FOR 400/500 SERIES UNITS			OPTIONAL	MTH		-			
	MOC :									
SL 525-23-11	COMMUNICATIONS - ATG 5000 SOFTWARE UPGRADE			OPTIONAL			-			
	MOC :									
SL 525-23-12	COMMUNICATIONS - ATG 5000 SOFTWARE UPDATE TO VERSION 2.8			OPTIONAL			-			
	MOC :									
SB 525-24-19 R02 24SB-19 : 525R2	CONCORDE LEAD ACID BATTERY INSTALLATION	KSNL		OPTIONAL	MTH 16-Aug-2019 HRS 4053.9 LDG 3575		-			Complete
	MOC : COMPLIED WITH - REMOVE 28 AMP HR NICAD BATTERY AND INSTALL 44 AMP HR CONCORD BATTERY AS PER SB525-24-19 TO INCLUDE UPGRADE KIT P/N SB525-19-1 FOR 44 AMP UPGRADE. UPDATE WEIGHT AND BALANCE.									
SB 525-24-22 24SB-22	TAILCONE ELECTRICAL GROUND STUD IMPROVEMENT			RECOMMENDED	MTH 27-May-2004 HRS 421		-			Complete
	MOC : COMPLIED WITH									
SB 525-24-23 24SB-23	AFT CABIN WIRE BUNDLE PROTECTION			RECOMMENDED	MTH 27-May-2004 HRS 421		-			Complete
	MOC : COMPLIED WITH									
SB 525-24-24 24SB-24	PANEL ASSEMBLY IMPROVEMENT	AAF		MANDATORY	MTH 01-May-2010 HRS 2263.6 LDG 2071		A/R			Complete
	MOC : COMPLIED WITH									
SB 525-24-25 24SB-25	NICKEL-CADMIUM BATTERY INSTALLATION			OPTIONAL	MTH		-			
	MOC :									
SB 525-24-27 24SB-27	AVIONICS EMERGENCY BUS RELAY IMPROVEMENT			DISCRETIONARY	MTH		A/R			
	MOC :									
SL 525-24-10	ELECTRICAL POWER - BATTERY TEMPERATURE INDICATOR GAGE BLANKING PLATE INSTALLATION			OPTIONAL			-			
	MOC :									
SB 525-25-19 25SB-19	EMERGENCY LOCATOR TRANSMITTER (ELT) WIRING MOD			OPTIONAL	MTH		-			
	MOC :									
SB 525-25-22 R01 25SB-22 : 525R1	GLARESHIELD LEATHER STRAP INSTALLATION			OPTIONAL	MTH		-			
	MOC :									
SB 525-25-23 R01	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-25-23 25SB-23	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION MOC :			OPTIONAL			A/R			
SB 525-25-24 25SB-24	AIRCELL ANTENNA INSTALLATION IMPROVEMENT MOC :			OPTIONAL	MTH		-			
SB 525-25-26 25SB-26	PASSENGER SEAT GEAR AND BACKREST LATCH PIN REPLACEMENT MOC :			OPTIONAL	MTH		-			
SB 525-25-34	EQUIPMENT/FURNISHINGS - OPTION FOR LARGER HEADSET HOOK MOC :			OPTIONAL			-			
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION MOC :			OPTIONAL			-			
SL 525-25-03 25SL-03	LEFT HAND TOILET SEAT BELT INSPECTION/INSTALLATION MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.	ICT		RECOMMENDED	MTH 19-Jun-2001 HRS 7		A/R			Complete
SL 525-25-04 25SL-04	TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARY BUCKLE PLASTIC HANDLE MOC : COMPLIED WITH	AFF		MANDATORY	MTH 01-May-2010 HRS 2263.6 LDG 2071		A/R			Complete
SL 525-25-05 25SL-05	INSPECTION OF THE BACKREST LATCH PLATES MOC : COMPLIED WITH - CW SL525-25-05. NO DEFECTS NOTED.	ICT		MANDATORY	MTH 04-Apr-2012 HRS 2440.1 LDG 2246		A/R			Complete
SB 525-26-01 26SB-01	FIRE BOTTLE IDENTIFICATION SLEEVE INSTALLATION MOC : COMPLIED WITH			MANDATORY	MTH 12-Jul-2006 HRS 1128		A/R			Complete
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING MOC :			MANDATORY	MTH		-			
SB 525-27-15 R01 27SB-15 : 525R1	FLAP OVERRIDE SWITCH INSTALLATION MOC : COMPLIED WITH			RECOMMENDED	MTH 27-May-2004 HRS 421		-			Complete
SB 525-27-18 27SB-18	ELEVATOR TRIM POINTER IMPROVEMENT MOC :			OPTIONAL	MTH		-			
SB 525-27-19 R01	ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION MOC :			MANDATORY	MTH		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-27-19 R02 <i>27SB-19</i>	ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION	ICT	MANDATORY	MTH 25-Nov-2014 HRS 3113.8 LDG 2777		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525-27-19 ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION, REVISION 2 DATED NOVEMBER 17, 2011. TRANS.									
SB 525-27-19 <i>27SB-19</i>	ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION		MANDATORY			A/R			
MOC :									
SB 525-27-20 <i>27SB-20</i>	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT		OPTIONAL	MTH		A/R			
MOC :									
SL 525-27-01 <i>27SL-01</i>	ELEVATOR ELECTRIC TRIM TAB ACTUATOR MOUNT INSPECTION	SMF	RECOMMENDED	MTH 09-Jun-2003 HRS 92		-			Complete
MOC : COMPLIED WITH									
SL 525-27-04 R01 <i>27SL-04 : 525R1</i>	FLAP PUSHROD SAFETY WIRE INSPECTION	ICT	RECOMMENDED	MTH 04-Apr-2012 HRS 2440.1 LDG 2246		A/R			Complete
MOC : COMPLIED WITH									
SL 525-27-09	FLIGHT CONTROLS - SPEED BRAKE ACTUATOR SCREW REPLACEMENT		OPTIONAL			-			
MOC :									
SB 525-28-11 R01 <i>28SB-11 : 525R1</i>	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	MCO	MANDATORY	MTH 02-Dec-2004 HRS 568		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS		INFORMATIONAL			-			
MOC :									
SB 525-29-11 R02 <i>29SB-11 : 525R2</i>	HYDRAULIC RELIEF VALVE INSPECTION		CANCELLED	MTH		A/R			
MOC :									
SB 525-29-14 R01	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT	KSGF	MANDATORY	MTH 09-May-2013 HRS 2640.2 LDG 2388		A/R			Complete
MOC : COMPLIED WITH - ACCOMPLISHED HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT SERVICE BULLETIN. IAW- CESSNA SB525-29-14. ALL OPS AND LEAK CHECKS GOOD WITH NO DEFECTS NOTED. NOTE: SERIAL NUMBER OF HYRAULIC VALVE HAS CHANGED FROM SN- 102 TO 102C PER SERVICE BULLETIN.									
SB 525-29-14	HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT		MANDATORY	MTH		A/R			
MOC :									
SB 525-29-15	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION		OPTIONAL			A/R			
MOC :									
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION INFORMATIONAL									
MOC :										
SL 525-31-04 <i>31SL-04</i>	TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 12 REVISION 2, AFD-3010 ADAPTIVE FLIGHT DISPLAY	SMF		MANDATORY	MTH 09-Jun-2003 HRS 92		A/R			Complete
MOC : COMPLIED WITH										
SB 525-32-25 <i>32SB-25</i>	BEARING REPLACEMENT			MANDATORY	MTH 25-Apr-2006 HRS 1039		A/R			Complete
MOC : COMPLIED WITH										
ASL 525-32-21 <i>32SLA21</i>	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1559-32-4, MAIN LANDING GEAR - BRAKE ASSEMBLY - P/N 2-1559-1 AND 2-1559-2 - CESSNA CITATION AIRCRAFT - INTRODUCTION OF A NEW BRAKE ASSEMBLY P/N 2-1559-3	AFF		MANDATORY	MTH 01-May-2010 HRS 2263.6 LDG 2071		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL INFORMATIONAL									
MOC :										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION	SGF		RECOMMENDED	MTH 15-May-2015 HRS 3308.2 LDG 2932		-			Complete
MOC : COMPLIED WITH - C/W SL CIL-32-03 (NLG UPLOCK) IAW SL CIL-32-03 INSTRUCTIONS, NO DEFECTS NOTED.										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL									
MOC :										
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION INFORMATIONAL									
MOC :										
SL 525-32-15 <i>32SL-15</i>	NOSE LANDING GEAR TIRE INSPECTION	SMF		MANDATORY	MTH 26-Aug-2002 HRS 75 LDG 70		A/R			Complete
MOC : COMPLIED WITH										
SL 525-32-17 R01 <i>32SL-17 : 525R1</i>	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SL 525-32-19 <i>32SL-19</i>	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056	PDK		RECOMMENDED	MTH 17-May-2010 HRS 2263.6 LDG 2071		A/R			
MOC : DEFERRED - OPERATOR ELECTED NOT TO COMPLY										
SL 525-32-20 <i>32SL-20</i>	MAIN LANDING GEAR DOOR PUSHROD SAFETY WIRE INSPECTION	PDK		RECOMMENDED	MTH 17-May-2010 HRS 2263.6 LDG 2071		A/R			
MOC : DEFERRED - OPERATOR ELECTED NOT TO COMPLY										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-32-23 R02	EMERGENCY GEAR RELEASE INSPECTION	SGF		MANDATORY	MTH 27-Nov-2012 HRS 2518.5 LDG 2308		-			Complete
MOC : COMPLIED WITH - C/W SL525-32-23 R2 (EMERGENCY GEAR RELEASE INSPECTION) IAW CESSNA CITATION SL525-32-23 R2 INSTRUCTIONS, NO DEFECTS NOTED.										
SL 525-32-23 32SL-23	EMERGENCY GEAR RELEASE INSPECTION			MANDATORY				A/R		
MOC :										
SL 525-32-27	LANDING GEAR - MAIN LANDING GEAR REPAIR									
MOC :										
SB 525-33-07 33SB-07	CHART LIGHT MODIFICATION			OPTIONAL	MTH					
MOC :										
SB 525-33-10	LIGHTS - WING TIP LED LIGHT MODIFICATION			OPTIONAL						
MOC :										
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL						
MOC :										
SB 525-34-40 R01 34SB-40 : 525R1	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION	MCO		OPTIONAL	MTH 02-Dec-2004 HRS 568			A/R		Complete
MOC : COMPLIED WITH										
SB 525-34-45 34SB-45	FLIGHT GUIDANCE COMPUTER (FGC)-3000 MOD 1			RECOMMENDED	MTH 01-Jul-2004 HRS 421					Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.										
SB 525-34-46 34SB-46	UNIVERSAL AVIONICS FLAT PANEL CONTROL DISPLAY UNIT UPGRADE TO MOD 8			MANDATORY	MTH 01-Jul-2004 HRS 421					Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.										
SB 525-34-48 34SB-48	ADAPTIVE FLIGHT DISPLAY (AFD) UPGRADE	SMF		RECOMMENDED	MTH 09-Jun-2003 HRS 92					Complete
MOC : COMPLIED WITH										
SB 525-34-51 34SB-51	VOR IMPROVEMENT	SMF		RECOMMENDED	MTH 09-Jun-2003 HRS 92			A/R		Complete
MOC : COMPLIED WITH										
SB 525-34-52 34SB-52	ATTITUDE INDICATOR AND HORIZONTAL SITUATION INDICATOR MODIFICATION	PDK		RECOMMENDED	MTH 17-May-2010 HRS 2263.6 LDG 2071					
MOC : DEFERRED - OPERATOR ELECTED NOT TO COMPLY										
SB 525-34-55 34SB-55	MARK V TERRAIN AWARENESS AND WARNING SYSTEM (TAWS) INSTALLATION			OPTIONAL	MTH					
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-34-56 34SB-56	MARK VIII TERRAIN AWARENESS ADWARNING SYSTEM (TAWS) INSTALLATION			OPTIONAL MTH			-			
MOC :										
SB 525-34-57 34SB-57	RADIO ALTIMETER CONVERTER UPGRADE			DISCRETIONARY MTH			-			
MOC :										
SB 525-34-60 34SB-60	GARMIN GNS-530A RADIO/FMS AND GTX-330D TRANSPONDER INSTALLATION			OPTIONAL MTH			-			
MOC :										
SB 525-34-63 34SB-63	MST-67A DIVERSITY TRANSPONDER INSTALLATION			OPTIONAL MTH			-			
MOC :										
SB 525-34-65 34SB-65	GARMIN GTX-330(D) TRANSPONDER SOFTWARE UPGRADE TO 4.01			OPTIONAL MTH			A/R			
MOC :										
SB 525-34-66 34SB-66	UNIVERSAL UNS-1K SOFTWARE UPGRADE TO 604.7			OPTIONAL MTH			A/R			
MOC :										
SB 525-34-67 R01 34SB-67 : 525R1	TERRAIN AWARENESS WARNING SYSTEM (TAWS) UPGRADE TO SOFTWARE LEVEL 1.13			OPTIONAL MTH			O/C			
MOC :										
SB 525-34-68 R02 34SB-68 : 525R2	FILE SERVER INSTALLATION AND MULTIFUNCTION DISPLAY (MFD) UPDATE FOR CHARTS AND XM SATELLITE WEATHER			OPTIONAL MTH			A/R			
MOC : - SERVICE BULLETIN ON HOLD.										
SB 525-34-84 R03	NAVIGATION - COLLINS FMS-3000 WIDE AREA AUGMENTATION SYSTEM (WAAS) WITH FMS 4.0 SOFTWARE UPDATES			OPTIONAL			-			
MOC :										
ASL 525-34-13 34SLA13	FLAT PANEL CONTROL DISPLAY UNIT INVERTER CIRCUITRY INTEGRITY TEST	BFI		MANDATORY MTH 05-Jan-2002 HRS 44			-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB CIB-34-04	ROCKWELL COLLINS ADAPTIVE FLIGHT DISPLAY UPGRADE	SGF		OPTIONAL MTH 12-Jul-2016 HRS 3654 LDG 3246			-			Complete
MOC : COMPLIED WITH - C/W CESSNA CITATION CIB-34-04 R&R PFD AND MFD IAW CIB-34-04 INSTRUCTIONS.										
SL 525-34-08 34SL-08	TRANSMITTAL OF BFGOODRICH ALERT SERVICE BULLETIN 78A	ICT		MANDATORY MTH 19-Jun-2001 HRS 7			A/R			Complete
MOC : COMPLIED WITH										
SL 525-34-09 34SL-09	TRANSMITTAL OF BF GOODRICH ALERT SERVICE BULLETIN #79	ICT		MANDATORY MTH 19-Jun-2001 HRS 7			A/R			Complete
MOC : COMPLIED WITH										
SL 525-34-10 R01 34SL-10 : 525R1	GNS-XLS MOD 7 SOFTWARE UPGRADE	SMF		RECOMMENDED MTH 09-Jun-2003 HRS 92			-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-34-16 34SL-16	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN KN 40-7 NAV CONVERTER			RECOMMENDED	MTH 27-May-2004 HRS 421		-			Complete
MOC : COMPLIED WITH										
SL 525-34-22 R01 34SL-22 : 525R1	UNS-1ESP FMS CAPACITOR UPGRADE	PDK		MANDATORY	DAYS 17-May-2010 HRS 2263.6 LDG 2071		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT. ITEM NOT INSTALLED										
SLA 525-34-04 34SLA04	KLN89B,KLN90B & KLN900 GPS INSTRUMENT LANDING SYSTEM APPROACH RESTRICTIONS	ICT		MANDATORY	MTH 19-Jun-2001 HRS 7		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	SGF		MANDATORY	MTH 02-Feb-2016 DAYS 3558.8 HRS 3156 LDG		-			N/A
MOC : NOT APPLICABLE - SL CIL-35-05 (ZODIAC OXYGEN MASK) N/A DUE TO AFFECTED MASKS LISTED IN ZODIAC SB MCF-SBU-35-001 APPENDIX I NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.										
SL 525-35-05	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
MOC :										
SL 525-35-06 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 525-35-06 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	SGF		MANDATORY	MTH 13-May-2013 HRS 2640.2 LDG 2388		-			N/A
MOC : NOT APPLICABLE - SL525-35-06 R2 (OXYGEN) DOES NOT APPLY DUE TO AFFECTED OXYGEN MASKS NOT INSTALLED IN AIRCRAFT. PILOT'S P/N MC10-16-101 S/N 116809 COPILOT'S P/N MC10-16-101 S/N 118938.										
SL 525-35-06	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SB 525-36-04 R01 36SB-04 : 525R1	PRECOOLER IMPROVEMENT			DISCRETIONARY	MTH		A/R			
MOC :										
SB 525-36-04 R02	PRECOOLER IMPROVEMENT	SGF		DISCRETIONARY	MTH 23-Mar-2017 HRS 3805.6 LDG 3368 ACH 2212.3		-			Complete
MOC : COMPLIED WITH - C/W SB525-36-04 (PRECOOLER IMPROVEMENT) IAW SB INSTRUCTIONS USING KITS P/N SB525-36-04-0 AND P/N SB525-36-04-2 AND PRECOOLERS P/N 9914402-6, LEAK CHECK OK.										
SB 525-36-04 R03	PNEUMATIC - PRECOOLER IMPROVEMENT			DISCRETIONARY			-			
MOC :										
SL 525-36-01 R01 LEFT 36SL-01 : L	PRECOOLER INSPECTION MODEL 525	BHM		RECOMMENDED	MTH 09-Jul-2006 HRS 1185.8 LDG 1170		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-36-01 R01 RIGHT 36SL-01 : R	PRECOOLER INSPECTION	BHM		RECOMMENDED	MTH 09-Jul-2006 HRS 1185.8 LDG 1170		-			Complete
MOC : COMPLIED WITH										
SB 525-38-01 38SB-01	PILOTS RELIEF TUBE IMPROVEMENT			OPTIONAL	MTH		-			
MOC :										
SB 525-52-08 R01 52SB-08 : 525R1	IMPROVEMENT FOR THE CABIN ENTRY STEPS			OPTIONAL	MTH		A/R			
MOC :										
SB 525-52-09 R01	CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION			OPTIONAL			A/R			
MOC :										
SB 525-52-09 52SB-09 : 525R1	CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
ASL 525-52-01 52SLA01	EMERGENCY DOOR INSPECTION	AFF		MANDATORY	DAYS 01-May-2010 HRS 2263.6 LDG 2071		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION	SGF		MANDATORY	MTH 05-Nov-2013 HRS 2779.1 LDG 2502		-			Complete
MOC : COMPLIED WITH										
SL CIL-52-02	DOORS - EMERGENCY EXIT DOOR INSPECTION			INFORMATIONAL			-			
MOC :										
SL CIL-52-03	DOORS - EMERGENCY ESCAPE HATCH INSPECTION	KSNL		MANDATORY	MTH 17-Mar-2022 HRS 4212.6 LDG 3677		-			Complete
MOC : COMPLIED WITH										
SB 525-53-07 R02 53SB-07 : 525R2	AFT BAGGAGE SECTION SKI OPTION INSTALLATION	*CF		OPTIONAL	MTH		-			
MOC :										
SB 525-53-20 R01 53SB-20 : 525R1	DISABLE THE COCKPIT MOUNTED RELIEF TUBE(S)	AFF		MANDATORY	DAYS 01-May-2010 HRS 2263.6 LDG 2071		A/R			Complete
MOC : COMPLIED WITH										
ASL 525-53-03 R01 53SLA03 : 525R1	RELIEF TUBE CORROSION			MANDATORY	MTH		BF/F BF/F			
MOC :										
ASL 525-53-04 R06 53SLA04 : 525R6	RELIEF TUBE CORROSION INSPECTION	AFF		MANDATORY	DAYS 01-May-2010 HRS 2263.6 LDG 2071		A/R			Complete
MOC : COMPLIED WITH										
SL 525-53-05 53SL-05	INTERCOSTAL DRAINAGE PATH INSPECTION	ICT		RECOMMENDED	MTH 04-Apr-2012 HRS 2440.1 LDG 2246		A/R			Complete
MOC : COMPLIED WITH - CW SL525-53-05. DRILLED 1/4 INCH RIVET FROM DRAIN HOLE.										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-53-06	UPPER TAILCONE SKIN INSPECTION ICT			MANDATORY	MTH 04-Apr-2012 HRS 2440.1 LDG 2246		A/R			Complete
	MOC : COMPLIED WITH									
SL 525-53-07	ACCESS PANEL DRAIN HOLE INSTALLATION SGF			RECOMMENDED	MTH 06-Jun-2014 HRS 2931.1 LDG 2626		-			Complete
	MOC : COMPLIED WITH - C/W SL 525-53-07 (ACCESS PANEL DRAIN HOLE) DRAIN HOLES ALREADY PRESENT PER STEP 2A IAW CESSNA CITATION SL 525-53-07 INSTRUCTIONS.									
SB 525-54-04 R01 <i>54SB-04 : 525R1</i>	FIREWALL BOX REPAIR			RECOMMENDED			-			N/A
	MOC : NOT APPLICABLE - SUPERSEDED PER REVISION 2.									
SB 525-54-04 R02	NACELLES/PYLONS - FIREWALL BOX REPAIR			RECOMMENDED			A/R			
	MOC :									
SB 525-54-05	NACELLES/PYLONS - MID FIREWALL FASTENER INSPECTION ICT			MANDATORY	MTH 05-Apr-2012 HRS 2440.1 LDG 2246		A/R			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SB525-54-05; MID-FIREWALL FASTENER INSPECTION.									
SB 525-57-12 <i>57SB-12</i>	LEADING EDGE TUBE REPLACEMENT SMF			RECOMMENDED	MTH 09-Jun-2003 HRS 92		-			Complete
	MOC : COMPLIED WITH									
SL 525-57-02 <i>57SL-02</i>	ACCESS DOOR DRAINAGE IMPROVEMENT PDK			RECOMMENDED	MTH 17-May-2010 HRS 2263.6 LDG 2071		-			
	MOC : DEFERRED - OPERATOR ELECTED NOT TO COMPLY									
SL WI-70-1008 E1	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-70-1008 E2	STANDARD PRACTICES - CONSUMABLE MATERIALS LIST - REVISION TO LINE MAINTENANCE MANUAL						-			
	MOC :									
SB FJ44-71-006-CN E1	CANCELED - ENGINE - COMPRESSOR SECTION INSPECTION (CSI) - NOTIFICATION			CANCELLED			-			
	MOC :									
SB FJ44-71-006-CN E2	CANCELED - ENGINE - COMPRESSOR SECTION INSPECTION (CSI) - NOTIFICATION			CANCELLED			-			
	MOC :									
SL 44-71-153 E1	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING						-			
	MOC :									
SL 44-71-153 E2	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING						-			
	MOC :									
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL								
	MOC :								
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL								
	MOC :								
SL WI-71-1129 E1	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL		CANCELLED						
	MOC :								
SL WI-71-1129 E2	CANCELED - POWER PLANT - BIT NO. 50 FAULT TROUBLESHOOTING -REVISION TO MAINTENANCE MANUAL		CANCELLED						
	MOC :								
SL 525-72-08 72SL-08	TRANSMITTAL OF WILLIAMS ROLLS SERVICE BULLETIN FJ44-72-050, ENGINE-DIFFUSER HOLLOW BOLT FUEL DRAIN INSTALL	SMF	MANDATORY	MTH 26-Aug-2002 HRS 75					Complete
	MOC :		COMPLIED WITH - NOT APPLICABLE						
SL 525-72-09 72SL-09	TRANSMITTAL OF WILLIAMS ROLLS SERVICE BULLETIN FJ44-72-052, ENGINE-IP COMPRESSOR ROTOR-REPLACE	MCO	MANDATORY	MTH 02-Dec-2004 HRS 568					Complete
	MOC :		COMPLIED WITH - PREVIOUSLY COMPLIED WITH.						
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL						
	MOC :								
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL						
	MOC :								
SB FJ44-05-002 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL						
	MOC :								
SB FJ44-05-002 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL						
	MOC :								
SB FJ44-72-022 R01 E1	REPAIR RIGHT-HAND SERVICE ADAPTER INSERT OF FRONT BYPASS DUCT		RECOMMENDED						
	MOC :								
SB FJ44-72-022 R01 E2	REPAIR RIGHT-HAND SERVICE ADAPTER INSERT OF FRONT BYPASS DUCT		RECOMMENDED						
	MOC :								
SB FJ44-72-022 R02-CN E1	CANCELED - ENGINE - FRONT BYPASS DUCT - REPAIR RIGHT HAND SERVICE ADAPTER INSERT		CANCELLED						
	MOC :								
SB FJ44-72-022 R02-CN E2	CANCELED - ENGINE - FRONT BYPASS DUCT - REPAIR RIGHT HAND SERVICE ADAPTER INSERT		CANCELLED						
	MOC :								
SB FJ44-72-022 R02 E1	FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT		RECOMMENDED						
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-022 R02 E2	FRONT BYPASS DUCT - REPAIR RIGHT-HAND SERVICE ADAPTER INSERT			RECOMMENDED			-			
	MOC :									
SB FJ44-72-029 R03 E1	1ST LP TURBINE NOZZLE ASSEMBLY-ADD OIL SCAVENGE SLOT			RECOMMENDED			-			
	MOC :									
SB FJ44-72-029 R03 E2	1ST LP TURBINE NOZZLE ASSEMBLY-ADD OIL SCAVENGE SLOT			RECOMMENDED			-			
	MOC :									
SB FJ44-72-041 R04 E1	ENGINE ζ HP TURBINE ζ REPLACEMENT OF BLADES AND BLADE RETAINERS / RE-IDENTIFICATION OF HP TURBINE DISKS AND ROTOR ASSEMBLIES			RECOMMENDED			-			
	MOC :									
SB FJ44-72-041 R04 E2	ENGINE ζ HP TURBINE ζ REPLACEMENT OF BLADES AND BLADE RETAINERS / RE-IDENTIFICATION OF HP TURBINE DISKS AND ROTOR ASSEMBLIES			RECOMMENDED			-			
	MOC :									
SB FJ44-72-042 R06 E1	INSTALL REAR MOUNT SLEEVE			OPTIONAL			-			
	MOC :									
SB FJ44-72-042 R06 E2	INSTALL REAR MOUNT SLEEVE			OPTIONAL			-			
	MOC :									
SB FJ44-72-051 R03 E1	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-051 R03 E2	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-051 R04 E1	REWORK NAMEPLATE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-051 R04 E2	REWORK NAMEPLATE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-051 R05 E1	NAMEPLATE - REWORK			RECOMMENDED			-			
	MOC :									
SB FJ44-72-051 R05 E2	NAMEPLATE - REWORK			RECOMMENDED			-			
	MOC :									
SB FJ44-72-054 R04 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05)			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-054 R04 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-054 R05 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-054 R05 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-054 R06 E1	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
	MOC :									
SB FJ44-72-054 R06 E2	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
	MOC :									
SB FJ44-72-066 R03 E1	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-066 R03 E2	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE (SUPERSEDED BY FJ44-72-066 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-076 R01 E1	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 R01 E2	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 R02 E1	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 R02 E2	IP COMPRESSOR STATOR - REWORK			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 E1	REWORK - ENGINE- COMPRESSOR STATOR (SUPERSEDED BY FJ44-72-076 R01)			OPTIONAL			-			
	MOC :									
SB FJ44-72-076 E2	REWORK - ENGINE- COMPRESSOR STATOR (SUPERSEDED BY FJ44-72-076 R01)			OPTIONAL			-			
	MOC :									
SB FJ44-72-079 R02 E1	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
	MOC :									
SB FJ44-72-079 R02 E2	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-083 R01 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R02)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R01 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R02)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R03 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R04)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R03 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R04)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R04 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R05)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R04 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R05)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R05 E1	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R06)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R05 E2	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R06)			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R06 E1	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL			-			
	MOC :									
SB FJ44-72-083 R06 E2	UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL			-			
	MOC :									
SB FJ44-72-087 R02 E1	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R03)			OPTIONAL			-			
	MOC :									
SB FJ44-72-087 R02 E2	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R03)			OPTIONAL			-			
	MOC :									
SB FJ44-72-087 R03 E1	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R04)			OPTIONAL			-			
	MOC :									
SB FJ44-72-087 R03 E2	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R04)			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-087 R04 E1	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R05)			OPTIONAL			-			
	MOC :									
SB FJ44-72-087 R04 E2	ENGINE - BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-087 R05)			OPTIONAL			-			
	MOC :									
SB FJ44-72-087 R05 E1	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1011 R01)			OPTIONAL			-			
	MOC :									
SB FJ44-72-087 R05 E2	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1011 R01)			OPTIONAL			-			
	MOC :									
SB FJ44-72-092 E1	ENGINE - 1ST LP TURBINE NOZZLE - REWORK			RECOMMENDED			-			
	MOC :									
SB FJ44-72-092 E2	ENGINE - 1ST LP TURBINE NOZZLE - REWORK			RECOMMENDED			-			
	MOC :									
SB FJ44-72-099 R01 E1	ENGINE - 6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-099 R01 E2	ENGINE - 6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-099 R02 E1	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R03)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-099 R02 E2	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R03)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-099 R03 E1	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-099 R03 E2	6 BOLT SPINNER - REPLACE (SUPERSEDED BY FJ44-72-099 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-099 R04 E1	6 BOLT SPINNER ζ REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-099 R04 E2	6 BOLT SPINNER ζ REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 R01-CN E1	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-108 R01-CN E2	SUPERSEDED - ACCESSORY DRIVE SHAFT - REPLACE (THIS SERVICE DOCUMENT IS NO LONGER AVAILABLE)			CANCELLED			-			
	MOC :									
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 R01 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY SB WISB-72-1037 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-108 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		-		5024.2	770.4
	MOC :									
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS		-		5000	746.2
	MOC :									
SB FJ44-72-111 R01 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-111 R01 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R02)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-111 R02 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION			RECOMMENDED	HRS		-		8524.2	4270.4
	MOC :									
SB FJ44-72-111 R02 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION			RECOMMENDED	HRS		-		6787	2533.2
	MOC :									
SB FJ44-72-111 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-111 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-112 E1	CANCELLED - ENGINE - ROUTINE PERIODIC INSPECTION - TIME EXTENSION			CANCELLED			-			
	MOC :									
SB FJ44-72-112 E2	CANCELLED - ENGINE - ROUTINE PERIODIC INSPECTION - TIME EXTENSION			CANCELLED			-			
	MOC :									
SB FJ44-72-123 R01 E1	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-123 R01 E2	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-129 R01-CN E1	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-129 R01-CN E2	CANCELED - ENGINE - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED	MTH HRS		DUE DUE DUE		5024.2	770.4
MOC :										
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED	MTH HRS		DUE DUE DUE		5000	746.2
MOC :										
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-149 R01 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-149 R01 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-149 R02 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED	MTH HRS		MPI MPI MPI		5024.2	770.4
MOC :										
SB FJ44-72-149 R02 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED	MTH HRS		MPI MPI MPI		5000	746.2
MOC :										
SB FJ44-72-149 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-149 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 44-72-325 R06 E1	ENGINE - 1ST LP TURBINE DISK - INSPECTION					-			
	MOC :								
SL 44-72-325 R06 E2	ENGINE - 1ST LP TURBINE DISK - INSPECTION					-			
	MOC :								
SL 44-72-325 R07 E1	1ST LP TURBINE DISK - INSPECTION					-			
	MOC :								
SL 44-72-325 R07 E2	1ST LP TURBINE DISK - INSPECTION					-			
	MOC :								
PSID WI-05-1000 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL			-			
	MOC :								
PSID WI-05-1000 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL			-			
	MOC :								
PSID WI-05-1000 R03 E1	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL			-			
	MOC :								
PSID WI-05-1000 R03 E2	UNSERVICEABLE PARTS - NOTIFICATION		INFORMATIONAL			-			
	MOC :								
PSID WI-72-1026 E1	FAN CASE - RUB INDICATIONS					-			
	MOC :								
PSID WI-72-1026 E2	FAN CASE - RUB INDICATIONS					-			
	MOC :								
SB WI-72-1011 R01 E1	BLEED VALVE ASSEMBLY - UPGRADE		OPTIONAL			-			
	MOC :								
SB WI-72-1011 R01 E2	BLEED VALVE ASSEMBLY - UPGRADE		OPTIONAL			-			
	MOC :								
SB WI-72-1011 E1	BLEED VALVE ASSEMBLY - UPGRADE		OPTIONAL			-			
	MOC :								
SB WI-72-1011 E2	BLEED VALVE ASSEMBLY - UPGRADE		OPTIONAL			-			
	MOC :								
SB WI-72-1037 R01 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE		RECOMMENDED			-			
	MOC :								
SB WI-72-1037 R01 E2	ACCESSORY DRIVE TOWERSHAFT - REPLACE		RECOMMENDED			-			
	MOC :								
SB WI-72-1037 R02 E1	ACCESSORY DRIVE TOWERSHAFT - REPLACE			MTH		-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-72-1037 E2	R02 ACCESSORY DRIVE TOWERSHAFT - REPLACE			MTH		-			
	MOC :								
SB WI-72-1037 E1	R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE					-			
	MOC :								
SB WI-72-1037 E2	R03 ACCESSORY DRIVE TOWERSHAFT - REPLACE					-			
	MOC :								
SB WI-72-1037 E1	R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE		RECOMMENDED			CSI			
	MOC :								
SB WI-72-1037 E2	R04 ACCESSORY DRIVE TOWERSHAFT - REPLACE		RECOMMENDED			CSI			
	MOC :								
SB WI-72-1041 E1	R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE		RECOMMENDED			-			
	MOC :								
SB WI-72-1041 E2	R01 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE		RECOMMENDED			-			
	MOC :								
SB WI-72-1041 E1	R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			MTH		-			
	MOC :								
SB WI-72-1041 E2	R02 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE			MTH		-			
	MOC :								
SB WI-72-1041 E1	R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE					-			
	MOC :								
SB WI-72-1041 E2	R03 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE					-			
	MOC :								
SB WI-72-1041 E1	R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE		RECOMMENDED			MPI			
	MOC :								
SB WI-72-1041 E2	R04 HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE		RECOMMENDED			MPI			
	MOC :								
SB WI-72-1041 E1	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE		RECOMMENDED			-			
	MOC :								
SB WI-72-1041 E2	HEAT EXCHANGER CLAMP ASSEMBLY - REPLACE		RECOMMENDED			-			
	MOC :								
SB WI-72-1044 E1	R01 BALANCE PISTON - REPLACE					-			
	MOC :								
SB WI-72-1044 E2	R01 BALANCE PISTON - REPLACE					-			
	MOC :								
SB WI-72-1044 E1	R02 BALANCE PISTON - REPLACE					-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-72-1044 E2	R02 BALANCE PISTON - REPLACE					-			
	MOC :								
SB WI-72-1044 E1	R03 BALANCE PISTON - REPLACE		RECOMMENDED			CSI			
	MOC :								
SB WI-72-1044 E2	R03 BALANCE PISTON - REPLACE		RECOMMENDED			CSI			
	MOC :								
SB WI-72-1044 E1	ENGINE - BALANCE PISTON - REPLACE			MTH		-			
	MOC :								
SB WI-72-1044 E2	ENGINE - BALANCE PISTON - REPLACE			MTH		-			
	MOC :								
SL WI-72-1080 E1	VISUALLY INSPECT THE 2ND LP TURBINE NOZZLE ASSEMBLY - REVISION TO ENGINE MANUAL					-			
	MOC :								
SL WI-72-1080 E2	VISUALLY INSPECT THE 2ND LP TURBINE NOZZLE ASSEMBLY - REVISION TO ENGINE MANUAL					-			
	MOC :								
SL WI-72-1128 E1	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-72-1128 E2	FAN ROTOR - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-72-1132-CN E1	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED					-			
	MOC :								
SL WI-72-1132-CN E2	CANCELED - ENGINE - APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL CANCELLED					-			
	MOC :								
SL WI-72-1132 E1	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-72-1132 E2	APPROVED ENGINE FUELS - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-72-1140 E1	INDUCTION HEATING - REVISION TO ENGINE MANUAL					-			
	MOC :								
SL WI-72-1140 E2	INDUCTION HEATING - REVISION TO ENGINE MANUAL					-			
	MOC :								
SL WI-72-1262 E1	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								
SL WI-72-1262 E2	APPROVED ENGINE FUEL - REVISION TO LINE MAINTENANCE MANUAL					-			
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-73-062 R01 E1	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE	KICT		RECOMMENDED	MTH 29-Nov-2022 HRS 4248.5 LDG 3701		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB FJ44-73-062 R1, ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY REPLACE.										
SB FJ44-73-062 R01 E2	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE	KICT		RECOMMENDED	MTH 29-Nov-2022 HRS 4248.5 LDG 3701		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB FJ44-73-062 R1, ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY REPLACE.										
SB FJ44-73-062 E1	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-73-062 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-73-062 E2	ENGINE FUEL AND CONTROL - FUEL FLOW TO OIL COOLER TUBE ASSEMBLY - REPLACE (SUPERSEDED BY FJ44-73-062 R01)			RECOMMENDED			-			
MOC :										
SB WI-73-1000 R01 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		-		5024.2	770.4
MOC :										
SB WI-73-1000 R01 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED	MTH HRS		-		5000	746.2
MOC :										
SB WI-73-1000 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-73-1000 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-74-1001 E1	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	SGF		MANDATORY	MTH 08-Nov-2017 HRS 3936.3 LDG 3491		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH NO. 1 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT, SERVICE BULLETIN WISB-74-1001.										
SB WI-74-1001 E2	IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT	SGF		MANDATORY	MTH 08-Nov-2017 HRS 3936.7 LDG 3492		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH NO. 2 ENGINE - IGNITION - IGNITER LEAD INSPECTION AND CLAMPING ARRANGEMENT, SERVICE BULLETIN WISB-74-1001.										
SB WI-75-1002 R01 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										
SB WI-75-1002 R01 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-75-1002 E1	R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH		CSI			
	MOC :									
SB WI-75-1002 E2	R02 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH		CSI			
	MOC :									
SB WI-75-1002 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
	MOC :									
SB WI-75-1002 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED			-			
	MOC :									
SL WI-76-1001-CN E1	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-76-1001-CN E2	CANCELED - ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL			CANCELLED			-			
	MOC :									
SL WI-76-1001 E1	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
	MOC :									
SL WI-76-1001 E2	ENGINE CONTROLS - VISUALLY INSPECT THE LP SHAFT TRIP SENSOR SYSTEM - REVISION TO THE LINE MAINTENANCE MANUAL						-			
	MOC :									
SL 525-77-02 77SL-02	TRANSMITTAL OF SAFE FLIGHT INSTRUMENT CORPORATION SERVICE LETTER NO. 58	SMF		RECOMMENDED	MTH 26-Aug-2002 HRS 75		-			Complete
	MOC : COMPLIED WITH									
SB FJ44-77-008 R03 E1	ENGINE INDICATING - REPLACE ITT PROBES WITH MID-LENGTH PROBE HARNESS			RECOMMENDED			-			
	MOC :									
SB FJ44-77-008 R03 E2	ENGINE INDICATING - REPLACE ITT PROBES WITH MID-LENGTH PROBE HARNESS			RECOMMENDED			-			
	MOC :									
SB FJ44-79-011 R01 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)			MANDATORY			-			
	MOC :									
SB FJ44-79-011 R01 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)			MANDATORY			-			
	MOC :									
SB FJ44-79-011 R02 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R03)			MANDATORY			-			
	MOC :									
SB FJ44-79-011 R02 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R03)			MANDATORY			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-79-011 R03 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)			MANDATORY			-			
MOC :										
SB FJ44-79-011 R03 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)			MANDATORY			-			
MOC :										
SB FJ44-79-011 R04 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R05 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
MOC :										
SB FJ44-79-011 R05 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE						-			
MOC :										
SB FJ44-79-011 R06 E1	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 R06 E2	OIL - MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY			-			
MOC :										
SB FJ44-79-011 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
MOC :										
SB FJ44-79-011 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
MOC :										
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
MOC :										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW									
				CANCELLED						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1998-25-02 <i>34AD-02</i>	APPLIANCE AD - BFGOODRICH SKYWATCH ICT			SKY497 MANDATORY	MTH 19-Jun-2001 HRS 7		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.										
FAA 2013-08-05 PARA (G)	INSPECTION AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM A/C COMPRESSOR HOUR METER	SGF		MANDATORY	DAYS 12-Jun-2013 HRS 2668.8 LDG 2415		-			Complete
MOC : COMPLIED WITH - C/W AD2013-08-05 (H) BY REPLACING COMPRESSOR DRIVE MOTOR BRUSHES P/N 1251171 A/C HOBBS: 1646.4. NEXT DUE A/C HOBBS: 2146.4.										
FAA 2013-08-05 PARA (H)	REPLACE AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM THE AIR CONDITIONING COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES	KSNL		MANDATORY	MTH 29-Jul-2021 HRS 4181.6 LDG 3654 ACH 2433.8		500		2933.8	Complete 500
MOC : COMPLIED WITH - C/W BY REPLACING WITH NEW MOTOR AND BRUSHES @ ACH: 2433.8 NEXT DUE: ACH: 2922.8										
FAA 2013-08-05 PARA (I)	DEACTIVATION AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM OF THE AIR CONDITIONING			MANDATORY			A/R			
MOC :										
FAA 2013-08-05 PARA (J)	RETURN AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM OF REPLACED PARTS AND REPORTING REQUIREMENT	SGF		MANDATORY	DAYS 16-Jul-2013 HRS 2681.5 LDG 2425		A/R			Complete
MOC : COMPLIED WITH - C/W AD2013-08-05 (J) R&R A/C COMPRESSOR MOTOR BRUSHES 06/12/2013 HOBBS: 1646.4. RETURNED BRUSH SETS TO CESSNA AIRCRAFT COMPANY. C/W AD2013-08-05 (J) R&R A/C COMPRESSOR MOTOR BRUSHES 06/12/2013 HOBBS: 1646.4. RETURNED BRUSH SETS TO CESSNA AIRCRAFT COMPANY.										
FAA 2013-08-05	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON CERTAIN P/N A/C COMPRESSOR MOTORS OR DEACTIVATION OF THE A/C SYSTEM	SGF		MANDATORY	MTH 12-Jun-2013 HRS 2668.8 LDG 2415		-			Complete
MOC : COMPLIED WITH - C/W AD2013-08-05 (H) BY REPLACING COMPRESSOR DRIVE MOTOR BRUSHES P/N 1251171 A/C HOBBS: 1646.4. NEXT DUE A/C HOBBS: 2146.4.										
FAA 1998-25-10 <i>25AD-01</i>	APPLIANCE AD - AIRCRAFT BELTS INC ICT			MANDATORY	MTH 19-Jun-2001 HRS 7		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	SGF		MANDATORY	MTH 22-Nov-2016 HRS 3744.3 LDG 3319 ACH 2198.5		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	SGF		MANDATORY	MTH 22-Nov-2016 HRS 3744.3 LDG 3319 ACH 2198.5		-			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	SGF		MANDATORY	MTH 22-Nov-2016 HRS 3744.3 LDG 3319 ACH 2198.5		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT	SGF		MANDATORY	MTH 22-Nov-2016 HRS 3744.3 LDG 3319 ACH 2198.5		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KSNL			MTH 11-Sep-2018 HRS 3979.8 LDG 3519		-			N/A
MOC : NOT APPLICABLE - ACCOMPLISHED FAA 2017-16-01 PARA (G), PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS, TESTS AND VERIFICATIONS AS APPLICABLE. EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT			MANDATORY			-			
MOC :										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS			MANDATORY			-			
MOC :										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	KSNL		MANDATORY	MTH 17-Mar-2022 HRS 4212.6 LDG 3677		-			Complete
MOC : COMPLIED WITH										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	KSNL		MANDATORY	MTH 17-Mar-2022 HRS 4212.6 LDG 3677		-			Complete
MOC : COMPLIED WITH										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
MOC :										
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
MOC :										
FAA 2005-17-11 26AD-01	PREVENT INCORRECT INSTALLATION OF WIRES			MANDATORY	MTH 12-Jul-2006 HRS 1128		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2019-08-13	FLIGHT CONTROLS - MODELS 525, 525A, AND 525B AIRPLANES WITH TAMARACK ACTIVE LOAD ALLEVIATION SYSTEM (ATLAS) WINGLETS INSTALLED IN ACCORDANCE WITH SUPPLEMENTAL TYPE CERTIFICATE (STC) SA03842NY - REVISE THE OPERATING LIMITATIONS SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) TO PROHIBIT FURTHER FLIGHT (SUPERSEDED BY 2020-24-06)		MANDATORY			-			
MOC :									
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	KSNL	MANDATORY	MTH 17-Mar-2022 HRS 4212.6 LDG 3677		-			Complete
MOC : COMPLIED WITH									
FAA 1997-05-03 R01 34AD-01 : 525R1	APPLIANCE AD - TO PREVENT DEVIATION FROM AN INTENDED FLIGHT PATH CAUSED BY INACCURATE INFORMATION FROM THE GPS		MANDATORY	MTH 01-Jul-2004 HRS 421		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE									
FAA 2001-23-17 34AD-04	APPLIANCE AD - GARMIN GNS 430	BFI	MANDATORY	MTH 05-Jan-2002 HRS 44		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2002-20-09 31AD-01	APPLIANCE AD - COLLINS AFD-3010 AFD UNITS	SMF	MANDATORY	MTH 09-Jun-2003 HRS 92		A/R			Complete
MOC : COMPLIED WITH									
FAA 2003-13-08 34AD-05	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS		MANDATORY	MTH 01-Jul-2004 HRS 421		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE									
FAA 2004-08-15 34AD-06	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS	PDK	MANDATORY	MTH 17-May-2010 HRS 2263.6 LDG 2071		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT DUE TO ONLY 5 PASSENGER SEATS INSTALLED									
FAA 2006-16-18 34AD-12	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI)	BHM	MANDATORY	MTH 15-Jan-2007 HRS 1382		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	SGF	MANDATORY	MTH 02-Mar-2015 HRS 3221.6 LDG 2865		-			N/A
MOC : NOT APPLICABLE - AD2012-02-08 (TCAS) N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED IN AIRCRAFT AT THIS TIME.									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	SGF	MANDATORY	MTH 22-Nov-2016 HRS 3744.3 LDG 3319 ACH 2198.5		-			N/A
MOC : NOT APPLICABLE									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	SGF	MANDATORY	MTH 02-Jun-2015 HRS 3322 LDG 2943		-			N/A
MOC : NOT APPLICABLE - AD2015-10-51 (AVIDYNE IFD) IS N/A DUE TO AFFECTED EQUIPMENT NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION IS REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-10-51	APPLIANCE AD - AVIADYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS									
				MANDATORY						
	MOC :									
FAA 2020-10-05	NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS	KSNL		MANDATORY	MTH 29-Jul-2021 HRS 4181.6 LDG 3654					N/A
	MOC :									
	NOT APPLICABLE - N/A BY INSTALLED EQUIPMENT LIST.									
FAA 1999-08-21 35AD-01	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEM	ICT		MANDATORY	MTH 19-Jun-2001 HRS 7		A/R			Complete
	MOC :									
	COMPLIED WITH									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	SGF		MANDATORY	MTH 02-May-2017 HRS 3827.7 LDG 3384 ACH 2221.9					N/A
	MOC :									
	NOT APPLICABLE - AD 2015-08-07 (G) (ZODIAC OXYGEN MASK) IS N/A DUE TO AFFECTED OXYGEN MASKS LISTED IN SB MXH-35-240 R7 APPENDIX I ARE NOT INSTALLED IN AIRCRAFT AT THIS TIME. NO FURTHER ACTION IS REQUIRED.									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	SGF		MANDATORY	MTH 02-May-2017 HRS 3827.7 LDG 3384 ACH 2221.9					N/A
	MOC :									
	NOT APPLICABLE - AD 2015-08-07 (H) (ZODIAC OXYGEN MASK) IS N/A DUE TO AFFECTED OXYGEN MASKS LISTED IN SB MXH-35-240 R7 APPENDIX I ARE NOT INSTALLED IN AIRCRAFT AT THIS TIME. NO FURTHER ACTION IS REQUIRED.									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	SGF		MANDATORY	MTH 02-May-2017 HRS 3827.7 LDG 3384 ACH 2221.9					N/A
	MOC :									
	NOT APPLICABLE - AD 2015-08-07 (ZODIAC OXYGEN MASK) IS N/A DUE TO AFFECTED OXYGEN MASKS LISTED IN SB MXH-35-240 R7 APPENDIX I ARE NOT INSTALLED IN AIRCRAFT AT THIS TIME. NO FURTHER ACTION IS REQUIRED.									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	SGF		MANDATORY	MTH 09-Dec-2015 DAYS 3520.8 HRS 3120 LDG					N/A
	MOC :									
	NOT APPLICABLE - AD2015-23-09 (ZODIAC OXYGEN MASK) N/A DUE TO AFFECTED MASKS LISTED IN ZODIAC SB MCF-SBU-35-001 APPENDIX I NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	SGF		MANDATORY	MTH 09-Dec-2015 DAYS 3520.8 HRS 3120 LDG					N/A
	MOC :									
	NOT APPLICABLE - AD2015-23-09 (ZODIAC OXYGEN MASK) N/A DUE TO AFFECTED MASKS LISTED IN ZODIAC SB MCF-SBU-35-001 APPENDIX I NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	SGF		MANDATORY	MTH 09-Dec-2015 DAYS 3520.8 HRS 3120 LDG		-			N/A
MOC : NOT APPLICABLE - AD2015-23-09 (ZODIAC OXYGEN MASK) N/A DUE TO AFFECTED MASKS LISTED IN ZODIAC SB MCF-SBU-35-001 APPENDIX I NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	SGF		MANDATORY	MTH 09-Dec-2015 DAYS 3520.8 HRS 3120 LDG		-			N/A
MOC : NOT APPLICABLE - AD2015-23-09 (ZODIAC OXYGEN MASK) N/A DUE TO AFFECTED MASKS LISTED IN ZODIAC SB MCF-SBU-35-001 APPENDIX I NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	SGF		MANDATORY	MTH 09-Dec-2015 HRS 3520.8 LDG 3120		-			N/A
MOC : NOT APPLICABLE - AD2015-23-09 (ZODIAC OXYGEN MASK) N/A DUE TO AFFECTED MASKS LISTED IN ZODIAC SB MCF-SBU-35-001 APPENDIX I NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	SGF		MANDATORY	MTH 09-Dec-2015 HRS 3520.8 LDG 3120		-			N/A
MOC : NOT APPLICABLE - AD2015-23-09 (ZODIAC OXYGEN MASK) N/A DUE TO AFFECTED MASKS LISTED IN ZODIAC SB MCF-SBU-35-001 APPENDIX I NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	SGF		MANDATORY	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		-			N/A
MOC : NOT APPLICABLE - AD2016-11-20 (G) DOES NOT APPLY DUE TO PBE P/N 119003-11 NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.										
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	SGF		MANDATORY	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		-			N/A
MOC : NOT APPLICABLE - AD2016-11-20 (H)(1) DOES NOT APPLY DUE TO PBE P/N 119003-11 NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	SGF		MANDATORY	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		-			N/A
MOC : NOT APPLICABLE - AD2016-11-20 (H)(2) DOES NOT APPLY DUE TO PBE P/N 119003-11 NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAAAD 2017-18-12	SGF	MANDATORY	MTH 17-Aug-2016 HRS 3659.9 LDG 3253 ACH 2151.4		-			N/A
MOC : NOT APPLICABLE - AD2016-11-20 DOES NOT APPLY DUE TO PBE P/N 119003-11 NOT INSTALLED IN AIRCRAFT, NO FURTHER ACTION REQUIRED.									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KALN	MANDATORY	MTH 16-Jan-2018 HRS 3944.8 LDG 3500 ACH 2305.1		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED AT THIS TIME.									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KALN	MANDATORY	MTH 16-Jan-2018 HRS 3944.8 LDG 3500 ACH 2305.1		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED AT THIS TIME.									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KALN	MANDATORY	MTH 16-Jan-2018 HRS 3944.8 LDG 3500 ACH 2305.1		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED AT THIS TIME.									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	KALN	MANDATORY	MTH 16-Jan-2018 HRS 3944.8 LDG 3500 ACH 2305.1		-			N/A
MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED AT THIS TIME.									
FAA 2008-03-10 53AD-01	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE	AAF	MANDATORY	DAYS 01-May-2010 HRS 2263.6 LDG 2071		-			Complete
MOC : COMPLIED WITH									
FAA 1999-07-04 E1	TO PREVENT HIGH PRESSURE TURBINE (HPT) DISK RIM FAILURE (P/N 55291)	ICT		MTH 19-Jun-2001			A/R		Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.									
FAA 1999-07-04 E2	TO PREVENT HIGH PRESSURE TURBINE (HPT) DISK RIM FAILURE (P/N 55291)	ICT		MTH 19-Jun-2001 HRS 7 LDG 6			A/R		Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.									



CESCOM 10 - Aircraft Status Report

Owner: **AIR FLITE, INC.**
 Aircraft Model: **525 - CJ1**
 Aircraft Serial: **525-0444**
 Unit: **0444** Reg No: **N525BR**
 Airworthiness: **19-Jun-2001**
 Print Date: **28-Apr-2023 8:56PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4253.8	3701	28-Apr-2023	.03
ENG 1	4229.6	3680	28-Apr-2023	.03
ENG 2	4253.8	3701	28-Apr-2023	.03
AIR COND	2433.8		28-Apr-2023	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
25FO-03 525 <i>25FO-03 : 525</i>	TAILCONE BAGGAGE EXTENSION FOR SKIS FACTORY OPTION	*CF		132 FO	MTH 19-Jun-2001		-			
25FO-05 525/B <i>25FO-05 : 525/B</i>	LOCATOR BEACON ARTEX FACTORY OPTION	*CF		175B FO	MTH 19-Jun-2001		-			
25FO-07 525/B <i>25FO-07 : 525/B</i>	PILOT RELIEF TUBE FACTORY OPTION	*CF		102B FO	MTH 19-Jun-2001		-			
25FO-53 525/C <i>25FO-53 : 525/C</i>	FIREBLOCKING-PASS. SEATS, AMP (ELITE TAILORING) FACTORY OPTION	*CF		118C FO	MTH 19-Jun-2001		-			
25FO-54 525/T <i>25FO-54 : 525/T</i>	TAILCONE BAGGAGE CARPET FACTORY OPTION	*CF		136T FO	MTH 19-Jun-2001		-			
33FO-04	TAIL FLOOD LIGHT INSTALLATION DEVORE FACTORY OPTION	*CF		54 FO	MTH 19-Jun-2001		-			
34FO-13	VOICE ANNUNCIATOR FACTORY OPTION	*CF		650 FO	MTH 19-Jun-2001		-			
35FO-02 G <i>35FO-02 : G</i>	EROS OXYGEN MASK & GOGGLE INST (EXCH) FACTORY OPTION	*CF		58G FO	MTH 19-Jun-2001		-			
38FO-01 525/C <i>38FO-01 : 525/C</i>	TOILET-FLUSH RH AFT NON-BELT(EXCH) FACTORY OPTION	*CF		130C FO	MTH 19-Jun-2001		-			
77FO-01 525 <i>77FO-01 : 525</i>	N1 COMPUTER C13232-1 SAFEFLIGHT FACTORY OPTION	*CF		680 FO	MTH 19-Jun-2001		-			